RIMONURA

DEC 1 5 1998

and the state of the	
CECT	4
	3 6 2 7 3

on this certificate.

## LAND CORNER RECORDATION CERTIFICATE

tis	enster	×	Office ounty	]
$T_{\varepsilon}$	gebic	:	ounty	S3.

For corners in	Filing Requirer	ment of Act 74, Mich. P.A		Ke	ceived	lor re	cord t	he	
Gogebic (County)	Located In:	Corner Code ##			day				
1. Public Land Survey	T 46N_R 45W_ T 47N_R 45W_ T 46N_R 46W_ (T 47N_R 46W_	A-1 A-13 M-1 M-13	A m., and recorded is  Liber 7 of Corners  page 63  Ramona Collyn Donuta						
E. Tropolity Community	TR		<del></del>	<u> †r113(1</u> 1		ater o		in	
•	T R		Register of	Deeds	Stamp (	k File	Numbe	er	
4. Lot No, Records. Private Claims			2 6	C D	E F	G H	1 J K	<u> </u>	
Section Corner 6, 1	l, 31 & 36; T.46-	47 N., R.45-46 W	. 3		+ + -		11-	12	
IRichard I. Drahn, in do hereby certify that under requirer in lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Couabove were in conformance with the Court of Law; established, re-est expressed below:	ments of P.A. 74. Michigan P.A. of formance with regulations and ns of the United States Department or tof Law and/or that the corner e rules of the Michigan Board of tablished, monumented, re-monagements.	f 1970, the corner points mention rules therefore as required in nent of the Interior, Bureau of Lapoints mentioned in lines 3, 4 an Land Surveyors or by a Decree on umented, recovered, found	ned 6 —18 and 7 —19 d 5 8 —19 of a 9 as 10 —3	20-29-	16 21 28	15	-2326	-2425	
NOTE: Not more than 4 corne	rs, all in the same town and	I range, may be recorded	11	-+	<del></del>	<del>                                     </del>	╀	1	

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt on 8/31/1847. Original B.T.s --- Y. Birch 18" S.34 E. 35 links (23.10') --- Cedar 12" N.66 W. 35 links (23.10') --- R.G. Campbell, on 7/26/35 recovered both BT's still scribed and placed a location poster on the south side of a 16" Black Ash.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the two original BT's. The first one is a badly decayed 20-22" Yellow Birch stump. The second one is now a downed, badly decayed 14-18" Cedar with evidence of the GLO blaze overgrowth still present.

Campbell's tag tree is now a broken 20-24" Black Ash stub bearing N.72 W. 9.0' from the original corner location. Unable to find his location poster.

Corner research on file with Gogebic County records.

Richard & Dealer 10/27/98

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4" X 4' solid aluminum rod with a  $3\frac{1}{4}$ " stamped aluminum cap and the following new bearing objects

9" Hemlock N.60 E. 15.35'
16" Hemlock N.13 E. 16.24'
6" Black Ash S.44 W. 20.55'
6' Steel sign rail S.79 W. 1.50'

A 3/4" iron pipe and two posts bears S.09 W., 12.9'

RICHARD
L DRAHN
LAND
SURVEYOR
No.
21564
LAND

Signed by Richard L. Wrahm

Date <u>October 6, 1998</u>

Surveyor's Michigan License No. 21564