LAND CORNER RECORDATION CERTIFICATE

Register's Office Society Ss.

Received for record the Filing Requirement of Act 74, Mich. P.A. 1970 19 TH day of AUGUST For corners in Gogebic A. D. 19 94 at 1:10 o'clock Located In: Corner Code ## P m., and recorded in T 47NR 47W H-3 Liber 5 Of COMMENS Public Land Survey 05 page 75 T R _ S-3 T _____ R _ amona Collins Deputy T _____ R __ Register of Deeds 2. Property Controlling S ____ R _ in Section ___ T ____ R ____ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. ___, Recorded Plat _____ 5. Private Claims __ May 11 John R. Garske , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

Original survey by William Ives in 1848. Set post. Original Bearing Trees: 12" spruce - S66°W -26 links; 6" fir - N41°W - 11 links.

Plat of Ironwood Homestead Addition 1947. Set concrete plat monument (1/2" iron rod encased in concrete 4 feet long). Concrete monument - NE - 46.39 feet; concrete monument - SE - 46.38 feet; fence post - South - 19.87 feet; fence post - NW - 26.40 feet.

1976 survey by Ewart C. Muller, RLS 15408, found original plat monument as described above and recorded in Liber 1 of Land Corners, page 187. B.T.'s: 10" aspen - N09°E - 35.14 feet; 6" elm - N33°W - 34.98 feet; 4" elm - S05°E - 43.97 feet.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a broken 4" square concrete monument and checked with the 6" elm (now a stump) from Muller's certificate. I updated the corner monument and accessories as noted below to state and county specifications. Only one of Muller's bearing trees (B.T.'s) exist at this time.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP

Approved

C. Description of monument for corner and accessories established to perpetuate locating the position of the

I set a 2 1/2" brass cap 2" below pavement in the found broken concrete monument (set with anchoring concrete). Brass cap is stamped: 1/4, S-3, S-10, T47N, R47W, 1994, RLS 28410. I established the following bearing trees and reference objects:

"X" on S.W. rim of manhole - N65°E - 33.06 feet.

Power pole#10-54/95 - S72°W - 100.71 feet

Clump of 4-10" maples (N.E. tree) - N18"W - 46.54 feet

Reference monument consisting of a 3/4" diameter x 4 ft. long aluminum rod with a 3 1/4" aluminum cap stamped to indicate corner position - Due South - 32.70 feet and steel sign post 1.70 feet away.

Signed by	Garabe	Date <i>E</i>	5/10/94
Λ	28410		

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971 REVISED MAY 14, 1975

OF HIC

JOHN R

GARSKĒ LAND SURVEYOR No. 28410