SURVEY &

SEP 29 1994

LAND CORNER RECORDATION CERTIFICATE

Register'	s Office	
Register' Gogebic	County	34

For corners in Goldwin Gogebic	_	rement of Act 74, Mich. P.A.	1970 Received for record the
(County)	Located In:	Corner Code ##	A. D. 19 94 at 4:10 o'clock
1. Public Land Survey S-27	T R T R	н-9	Liber 5 of Corners on page 127 Ramena Columa Operatu
in Section S	TR		Register of Deeds
	TR		Register of Deeds Stamp & File Number
4. Lot No. , Records Private Claims One-quarter corner co			A B C D E F G H I J K L M
I, John R. Garske , in do hereby certify that under requirer in lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Cou above were in conformance with the Court of Law; established, re-est expressed below:	nents of P.A. 74, Michigan P.A. formance with regulations an is of the United States Depart it of Law and/or that the corne rules of the Michigan Board o	d rules therefore as required in the tment of the Interior, Bureau of Land or points mentioned in lines 3, 4 and 9 of Land Surveyors or by a Decree of a	d 6 18 17 16 15 14 13 6 7 5 8 19 20 21 22 23 24 24
NOTE: Not more than 4 corner on this certificate.	s, all in the same town ar	nd range, may be recorded	11 12 31 32 33 34 35 36

Description of original monument and accessories and/or subsequent restoration:

Original survey by William Ives, D.S., in 1848. Set wood post. Original bearing trees: Spruce 8" - S08°W, 15 links; Fir 5" - N04°W, 12 links.

The 1/4 corner position was found by Ewart C. Muller, RLS 15408 in June 1976 and marked by a 1/2" iron in 4" diameter by 48" long concrete monument. The corner was recorded in liber 1 of land corners P. 188. Accessories: P. pole - N75°E, 46.10 feet; P. pole - S60°E, 54.00 feet; P. pole - due south - 27.89 feet.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a P.K. nail marking the corner position which checks with the witnesses in the certificate. The monument was destroyed during road excavation. I updated the corner as noted below to bring it up to county and state specifications.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP

Approved

adard R. Drahn 9/14/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the found P.K. nail with a 2 1/2" brass cap with a 2" stem set in anchoring cement 1 1/2" below pavement. Cap is stamped S-22, S-27, T47N, R47W, 1/4, 1994, RLS 28410. I established the following reference objects: One reference monument consisting of a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position as follows: R.M. - N33°E, 20.03 feet - with a steel sign post 1.16 feet away; P. pole - S65°W, 56.05 feets P. pole - S07°W, 27.83 feet; P. pole - S61°E, 53.95 feet.

8/29/9

LAND SURVEYOR No.

John R. Garske

28410

APPROVED BY MICHIGAN STATE TO ABO WELLAND SURVEYORS AND 197