SURVEY& REMONUMENTATION

SEP 2 9 1994

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Gogebic County

Register's Office

For corners in	Filing Requir	rement of Act 74, Mich. P.A	A. 1970 Received for record the	
Gogebic (County)	Located in:	Corner Code ≠≠	A. D. 19 74 at 4:00 o'clock	
Public Land Survey	T <u>47N</u> R <u>47W</u> T R T R	L-5	Pm., and recorded in Liber F of CORNERS on page 116	
 Property Controlling in Section Miscellaneous Property in Sec. 	T R S T R S T R S T R S T R		Register of Deeds Stamp & File Number	U
5. Private Claims			A B C D E F G H I J K	<u> </u>
I, John R. Garske , do hereby certify that under require lines 1 and 2 above were in current manual of survey instruct Management or by a decree of a dabove were in conformance with Court of Law; established, reexpressed below:	irements of P.A. 74, Michigan P.A. conformance with regulations are tions of the United States Depar Court of Law and/or that the corner the rules of the Michigan Board of the rules of the Michigan Board of the Michigan Board of the rules of the Michigan Board of	June 22 , 19 94 of 1970, the corner points mention ad rules therefore as required in terment of the interior, Bureau of La er points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of monumented, recovered, found	ned the and 7 13 17 16 15 14 16 15 14 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16	12-13-13-24-25-36-36-36-36-36-36-36-36-36-36-36-36-36-
	onument and accessories and	d/or subsequent restoration:		

- On August 25, 1848, William Ives set a wood post from which a B. ash 4" bears N53°E, 22. links and a Fir 6" bears S40°W, 07 links.
- 1938 survey by U.S.D.A. Set a 5" x 42" concrete monument with stamped bronze cap 8" below road surface from which a fence post N47°E, 46.38 feet; P. pole - S45°E, 39.55 feet; fence post -S47°W, 46.46 feet.
- August 1988 survey by J.R. Garske, RLS 28410. Re-established corner from M.D.O.T. Highway plans. Set P.K. nail at corner location as per recordation certificate L. 3, Pg. 262.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found a P.K. nail marking corner position and checked with witnesses from my previous recordation certificate. I dug up road at the corner location and found a 3/4" x 8" iron pin resting atop of a broken concrete monument 12" below road surface. I updated the corner as noted below to bring it up to county and state specifications.

Act 74 research on file with County Register of Deeds Office.

PEER GROUP Approved 9/14/94

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I reset the found 3/4" x 8" iron pin inside a 2 1/2" x 9" aluminum pipe with a brass cap on top encased in 8" x 12" of concrete, brass cap is stamped: 1/4; S-12; S-13; T47N, R47W, 1994, RLS 28410. I established the following bearing trees and reference objects: A reference monument consisting of a 2 1/2" x 30" aluminum pipe with a 3 1/4" aluminum cap stamped to indicate the corner position as follows: N46°W, 51.22 feet with steel sign post 1.42 feet away; 13" spruce S27°W, 73.51 feet; 15" R. pine N34°W, 55.10 feet; P. pole #12 - 49/05 - N46°E, 45.51 feet

Surveyor's Michigan License No. .

JOHN R GARSKE LAND URVEYO

No.

FED No. J-23