			Reguter's Office ss.
		ORNER RECORDATION CERTIFICA	,
Filing Rec	quirement of Act 74, Mich	i. P.A. 1970	-2 MD day of October
			A. D. 19 20 at 10:50 o'clock
Gogebic (County)	Located In:	Corner Code #	Am., and recorded in
1. Public Land Survey	T48 N R45 V	V. L-11	Liber 8 OF CORNERS
1. Public Land Survey	T R	<u> </u>	or page 40
	TR_	SURVEY &	Hamone Rulem Deputy
2. Property Controlling	TR S T R	EMONUMENTATION	Register of Docas
in Section	S T R	JAN 0 5 2001	
3. Miscellaneous	S T R	- JAIL 0 2 2001	Register of Deeds Stamp & File Number
Property in Sec.	S T R	= SECTION	
4. Lot No, Red 5. Private Claims			A B C D E F G H I J K L
V. 1 HVate Claims			1 2 6 5 4 3 2 1
¼ Corner 25 & 36;	T.48 N., R.45 W.		3
I, Richard L. Drahn , in a field survey on Sept 12, 2000 do hereby state			4 7 8 9 10 11 12
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points			
			7
		nance with the rules of the Michigar of Law; established, re-established,	
monumented, recovered, fou		or caw, established, re-established,	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			1 29 28 27 26 25
			1
			13 31 32 33 34 35 36
A. Description of original m	nonument and accessories	and/or subsequent restoration:	
		•	
Original corner establishe Tamarack	ed by Austin Burt on 9/14 10" S.32° E.	4/1848. Original bearing trees: 15 links (9.90')	
Tamarack	10* N.40° W.	07 links (4.62')	
Limpert, Hellan & Beck, Location poster on the S	on 4/11/35 recovered a 1 SW SIDE OF A 5" Cedar N გმუ	O' Tamarack, still scribed, laying NW 碑, 20 feet from the Spruce stake.	5ft. from a Spruce stake. They placed a
B. Description of corner evid	,	d applied in restoring or reestablishin	a corpor
			•
4.62'. No evidence rem N.48° E., 18.0 feet from	nains of the SE bearing tree of the original corner location	<ul> <li>Recovered the 1935 location position.</li> <li>The 1.30 chain distance west from</li> </ul>	ns of the Tamarack bearing tree at N.40° W., ter on the SW side of a 16" Cedar bearing om corner to "leave beaver meadow, SW" coord with the field notes of the original
A 4" squared Cedar post	t bears S.53° E: 79 feet fr	om the original corner location.	
		_	
Corner research on the A	with Gogebic County reco	iua.	
C. Description of monumen	nt for corner and accessori	ies established to perpetuate locating	the position of the corner:
At the corner position I s blazed and scribed bearing	set a %" X 48" solid alum ng trees: (measurements t	inum rod monument with a $3\ \%$ " stataken to a $10p$ nail in the side of the	rnped aluminum cap and the following new tree)
Cedar	12" N.83° E.	49.13'	THE STATE OF THE S
Cedar	7" S.02° W.	67.92′	RICHARD
Northerly high poil Steel sign rail	nt of a large rock bears S. 6' N.27° E.	78° E. 4.1 feet 2.12'	L. DRAHN
Steel sign rail	6' N.88° W.	2.06'	LAND SURVEYOR
		T() 1000	
	^ ^	CONTAIN BEREIKSEL	21564
Signed by To Signed	$\varphi_{\lambda}()$		LAND
1.50.00	No Carn	Date September 27, 2000	The state of the s
Surveyor's Michigan License	No. 21564	FORM APPROVED BY MICHIGA	N STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
USFS V-23			REVISED MAY 14,1975 REVISED JAN., 1983