SURVEY & REMONUMENTATION

OCT 0 3 1996

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Register'	's Office	
Register' Gogebic	County	85

Received for record the Filing Requirement of Act 74, Mich. P.A. 1970 day of JUNE

Fo	or corners in	•		day of June
******	Gogebic	Located In:	Corner Code ##	A. D. 19 96 at 9:40 o'clock
•	(County)	т <u>48N</u> я <u>47W</u>	K-12	Am., and recorded in
1.	Public Land Survėy	T R T R T R		Camora Couins peput
2.	Property Controlling in Section	S T R S T R		Register of Deeds
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
5.	Private Claims  1/4 cor. comm  John P. Goss hereby certify that under rec	to sects. 35 & 3	6 May 11 , 19 96 of 1970, the corner points mention	2 6 5 4 3 2 3 4 7 8 9 10 11 12 oned 6
Ma ab Co	rrent manual of survey instra anagement or by a decree of ove were in conformance wi	n conformance with regulations a uctions of the United States Depa a Court of Law and/or that the corn th the rules of the Michigan Board re-established, monumented, re-	rtment of the Interior, Bureau of L er points mentioned in lines 3, 4 a of Land Surveyors or by a Decree	Land 7
NC	OTE: Not more than 4 c on this certificate.	orners, all in the same town a	nd range, may be recorded	11 12 31 32 33 34 35 36
Α	Description of original	monument and accessories ar	d/or subsequent restoration:	

Original corner established by William Ives on Sept. 11, 1848. Set post. S 140 E Original Bearing trees: Black Ash 10" ll links 14" N 250 W Cedar 15 links

John R. Garske and John P. Goss set a railrooad spike at the corner location in 1991 and recorded it in Liber 3 on page 415 of Land Corners for Gogebic County. The following reference objects were established: 7" Red Maple- N 76° E-75.66'; P.Pole- S 16° E-30.38'; Nail with cap in pavement- Due North- 16.06'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

At 6 inches below gravel surface of roadway I found the railroad spike and it checked with the witnesses in Garske and Goss certification. I updated the corner monument and accessories as noted below to state and county specification.

Act 74 reach on file.

<b>)</b> .	Description of monument for corner ar	nd accessories established to perpetuate locating the p	osition of the corner:
	I replaced the railroad	spike at 6 inches below surface	with a 5/8" by 24"
	rebar capped with a 3½"	dia. aluminum cap stamped as fol	lows: County Remonumenta-
	tion; T.48 N., R.47 W.,	1/4; S-35, S-36; 1996; P.S. 2350	9. I established the
	following bearing trees		MANTENER

N 76° E D.H.Nail in 7" Red Maple 75.661 D.H. Nail in P. Pole S 16° E 30.38' D.H. Nail in 5" N. Pine S 38° W 52.47' Reference Monument consisting of 22" by 30" Aluminum monument with a 3½" aluminum cap stamped to indicated corner postion.

S 38° E 53.84' with a 6' rail and s
at 0.97'.

53.84' with a 6' rail and sign

Signed by Surveyor's Michigan License No. \_ \_23509\_

23509

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

Fed. No. X-21

LAND SURVEYOR

No.