## SURVEY & REMONUMENTATION

OCT 0 3 1996	
COMMISSION LAND CORNER RECORDATION CER	REGister's Office Sec.
For corners in Filing Requirement of Act 74, Mich.	- Sond Chillian
Gogbeic Located In: Corner Code ##	day of August
(County)	A. D. 1996 at 10:30 o'clock
1. Public Land Survey T 48N R 48W G-1	A m., and recorded in
Т <u>49N R_48WG-13 .</u> Т R	Liber 5 of CORNERS
T R	00 page 405
2. Property Controlling S T R	Rogister of Dock
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
Property in Sec. S T R	Tregister of beeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L
5. Private Claims	A B C D E F G H I J K L
Sec. cor. comm. to sec's 3,4,33 & 34	3
i. John P. Goss , in a field survey on June 15 19 96	4 7 4 9 10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points men	ntioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required current manual of survey instructions of the United States Department of the Interior, Bureau of	lin the ° -18-+-17-+-16-+-15-+-1413-
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decr	4 and 5
Court of Law; established, re-established, monumented, re-monumented, recovered, fou	ree of a gind as 9
expressed below:  NOTE: Not more than 4 corners, all in the same town and range, may be recorded	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
on this certificate.	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration	13
Original corner established by Wm. A. Burt in 18	
Original bearing trees: Fir 12" N 33° W 9 links	s
Lynn 9" N 59° W 28 link	S
No original evidence found due to road construct:	ion.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
Found 5/8 inch rebar in ceterline of Lake Road and road to the North.  This corner position shown on Gogebic County Road Commission Plan of	
1928 for Lake Road. The corner has been used in various surveys and	
is generally accepted as the Section corner by area residents.	
I accepted this corner position as the most probable location of the true section corner. I updated the corner monument and accessories	
as noted below to state and county specification.	
Act 74 research on file.	
A PUER &	RINIP EPERCELAL.
·R D D D D D D D	D. Alg/96
COURT	X BATTLAUMININA
C. Description of monument for corner and accessories established to perpetuate to	ocating the position of the corner:
At 2" below asphalt surface I set a 22" brass ca	
5/8" rebar. Cap is stamped T.48-49 N., R.48 W.; 1996, P.S. 23509. I established the following be	earing trees and references
obects.	OF MICHIGANIA
D.H. Nail in 7" Maple N 31° E 42.30' D.H. Nail in 5" Basswood N 31° W 41.67' D.H. Nail in P.Pole S 58° W 76.77'	JOHN P.
D.H. Nail in P.Pole S 58° W 76.77'	GOSS X
Reference Monument consisting of a $2\frac{1}{2}$ " by 30" Aluminum monument with a $3\frac{1}{4}$ " aluminum cap,	SURVEYOR
stamped to indicated corner position.	23509 23509
S $01^{\circ}$ E- 43.55', with 6' rail and sign 0.92'.	MINISTED LAND SUM
Signed by John P Loss Date I	Tune 21, 1996
Surveyor's Michigan License No. 23509	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1971