FEB 1 0 2000

LAND CORNER RECORDATION CERTIFICATE

LIBER 612 PAGE 387 GRATIOT CO. MICH. RECORDED

CECTION

Filing Requirement of Act 74, Mich. P.A. 1970

→ 99 AND 24 AM 11 09

2

3

5

8 q

10

11

12 -31

13

6

7

18

19

-30

5

➂

17

20

29

32

À

9

16

21

28

33

3.

-10

22

27

34

2

11

23

26

35

1

12

13

24

25

36

2EAHAIA			33 1100 21 1111 22 00	
For corners in GRATIOT (County)		Located In:	Corner Code #	Genet M. Jones REGISTER OF DEEDS
WASHINGTON TWP		•		() SEODIEK OF DECOS
Public Land Survey		T 9N R 2W T R T R T R	D-4	
2. Property Controlling in Section	\$ s	TR		
3. Miscellaneous	s	TR		Register of Deeds Stamp & File Number
Property in Sec.	s	TR		
4. Lot No, 5. Private Claims	Record	ed Plat		A B C D E F G H I J K E N

, in a field survey on June 02, 1999 & 1999, DAVID R. LOHR do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- 1. CORNER NOT SET IN GLO SURVEY.
- 2. CORNER REFERENCED IN SURVEY BY R.J. FRAKER, COUNTY SURVEYOR, DATED MAY 1867 ON PAGE 120 OF "SURVEY FIELD BOOKS -T9N, R2W" ON FILE AT GRATIOT COUNTY REGISTER OF DEEDS. NO MENTION OF MONUMENT. ELM 12", S 63 1/2° W, .34 CH. (22.44')

ELM 16", N 76° E, .48 CH. (31.68')
SURVEY SHOWS DISTANCE NORTH OF 39.95 CH. (2636.70') AND SOUTH OF 39.94(2636.04'). NO DISTANCES GIVEN EAST OR WEST.

- 3. NO OTHER REFERENCES FOUND.
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

SEARCHED AT APPARENT LOCATION OF CORNER AND FOUND NO EVIDENCE OF CORNER. REVIEW OF SURVEY BY COUNTY SURVEYOR FRAKER IN 1867, INDICATES THAT CORNER MAY HAVE BEEN SET MIDWAY ON NORTH-SOUTH 1/4 LINE INSTEAD TRAVERSE OF OF AT INTERSECTION OF 1/4 LINES BECAUSE NO DISTANCES ARE GIVEN IN EAST OR WEST DIRECTION. ENTIRE SECTION INDICATES THAT FRAKER'S POSITION (MIDWAY ON N-S 1/4 LINE) WOULD FALL 11 FT. (3.35m) EAST OF OCCUPIED BRUSH ROW TO SOUTH AND 33 FT. (10.059m) NORTH OF C/L OF TRACKS. OLD FENCES LIE ON BOTH SIDES OF TRACK BEING 48.7 FT. (14.84m) NORTH AND 32.6 FT. (9.937m) SOUTH OF C/L OF TRACK HOWEVER, DEEDS ON ADJOINING PARCELS DESCRIBE RAILROAD ROW TO BE 50 FT. (15.24m) NORTH AND 33 FT. (10.059m) SOUTH OF C/L OF TRACK WHICH IS ABOUT WHERE FENCES LIE. RAILROAD WAS CONSTRUCTED ABOUT 1886, ABOUT 20 YEARS AFTER FRAKER'S SURVEY OF 1867. CORNER DETERMINED TO BE LOST. SET CORNER AT INTERSECTION OF 1/4 LINES, WHICH FALLS ABOUT 12 FT. (3.658m) EAST OF OCCUPATION LINE TO SOUTH AND 14 FT. (4.27m) SOUTH OF C/L OF R.R. TRACKS. THIS POSITION NOT ESTABLISHED BY ORIGINAL GOVERNMENT SURVEYORS. SET CORNER ACCEPTED AS BEST AVAILABLE EVIDENCE OF THE POSITION OF THE CORNER. SET STANDARD GRATIOT COUNTY REMONUMENTATION PIPE WITH BRASS CAP AT INTERSECTION OF THE 1/4 LINES, 14 FT. (4.27m) SOUTH OF CENTERLINE OF RAILROAD TRACKS.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: D-4: TOWN 9 NORTH, RANGE 2 WEST, WASHINGTON TOWNSHIP, GRATIOT COUNTY. SET STANDARD GRATIOT COUNTY REMONUMENTATION PIPE WITH BRASS CAP AT INTERSECTION OF 1/4 LINES. WITNESSED BY:

SET N/T #30090, E/S 6"(150mm) MAPLE N 02° E, 35.43' (10.800 m) SET N/T #30090, S/S 6"(150mm) ELM, N 89° E, 17.77' (5.416 m) и 75° W, 36.99' (11.276 m) TRAV. PT. #1103 (#4 REBAR), N 59° W, 84.37' (25.717 m) SET N/T #30090, N/S 3"(75mm)ELM, S 07° E, 20.30′ (6.186 m) STEEL CABLE POST, NORTH, 11.52' (3.510m) SOUTH RAIL OF R.R. TRACK,

BEARINGS GIVEN ARE MAGNETIC. STANDARD MONUMENTATION CONSISTS OF A BERNTSEN STAINLESS STEEL 30"(762mm)X 2 3/8"(0.65mm)PIPE WITH A ERASS CAP STAMPED

"GRATIOT COUNTY REMONUMENTATION", P.S. #30090.

Surveyor's Michigan License No. 30090

Signed by

Date

ACCEPTED BY THE GRATIOT COLINATY AND ENGLISH MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871 GROUP AS THE OFFICIAL CORNER UNDER MIN REVISED MAY 14, 1975 REVISED JAN., 1985 REVISED JON., 1985 REVISED OCT, 1985 ADAPTED FOR WORD PROCESSING JAN, 1999 PUBLIC ACT 345 OF 1990 AT A MEETING HELD

Dem 6/c William Tingley, PS, Chairman

OF MICHIGAN

DAVID R.

LOHR

PROFESSIONAL

No. No.