班品 2 8 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

'98 DEC 22 AM 10 53

For corners in SECTI	ON	Located In:	Comer Code #	1		\sim			_	•	
Gratiot		Township		REGISTER OF DEEDS							
1. Public Land Survey		T 9N R 3W T R T R	M-5								
 Property Controlling in Section Miscellaneous Property in Sec. 	\$ \$ \$	T R		Reg	Register of Deeds Stamp & File Number						
4. Lot No, F	Recorded	Plat			1 A	B (C D	E F (s H 1	JK	L M
5. Private Claims				·	2	6	5	4	3	2	1
I, William G. Tingl	ey	, in a fiek	d survey on <u>January 28th,</u> in P.A. of 1970, the corner points	19 <u>98</u> ,	3 -	7	8	9	10	11	12
in lines 1 and 2 above we current manual of survey is	uired in the au of Land	6	18	17	16	15	14	13			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, above were in conformance with the rules of the Michigan Board of Land Surveyors or by a DecCourt of Law; established, re-established, monumented, re-monumented, recovered, for expressed below:					7 8	19	20	21	22	23	24
NOTE: Not more than		s, all in the same tov	vn and range, may be recor	rded	10	30	29	28	27	26	25
	nal monur	nent and accessories tes	and/or subsequent restoration	on:	12	31	32	33	34	35	36
•				book							
1878, R.J. Fraker, F Sleigh Shoe Co	tecord of l or-New Co	Maple 18 S51°E. 4 Cotton 30" N25°35 Minutes of Survey, Lib	5E. 81 1/2 ft. per B, Page 272 & Field Book ce of record, 1.50 chs S. of c en)								

West of the centerline of County Road #521 (20' asphalt). Corner was re-established from M.D.O.T. right-of-way for Gratiot County State Trunkline M-57, Page 32. Additional information was obtained from a survey by C.B. Fraker in September 1866, Page 12 of The "Record of Minutes of Surveys Book", for Fulton Township, located at the office of the Drain Commissioner of Gratiot County.

S.W. Corner Section 7, T9N-R2W Az. 04° 99.00'

Center of Storm Sewer Manhole Cover Az. 114° 17.70'ACCEPTED BY THE GRATIOT COUNTY CHRYEY

Buried Telephone Cable Junction Box Az. 162° 88.20' GROUP AS THE OFFICIAL CO.

Set Nail w/R.L.S. Tag in south side of Power Pole Az. 284° 73.34 PUBLIC ACT 345 0F 1990 AT A MELLI:

D. 3/16

Set 5/8" Re-Rod w/R.L.S. Cap #21273 on range line and 99.00' South of the S.W, Corner of Section 7, T.9 N., R.2 W. Corner is 0.4' West of the centerline of County Road #521 (22' asphalt). Corner was re-established from M.D.O.T. right-of-way Book for Gratiot

Set 5/8" Re-Rod w/R.L.S. Cap #21273 on range line and 99.00' South of the S.W. Corner of Section 7, T. 9 N., R.2 W. Corner is 0.4'

Date

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 5/8" rerod with faded yellow, illegible cap just below pavement. •

(no witnesses given) July 29, 1980, John I. Nelson, Land Corner Recordation Certificate, Liber 1, Page 507

Found nail & tag #21273 East side power pole N80°W 72.95 Feet Center of storm sewer grate S85°E 17.7± Feet Northwest corner telephone riser box S35°E 87.93 Feet A05 T9N-R2W **NORTH** 99.00 Feet

Description of monument for corner and accessories established to perpetuate locating the position of the co Set s

standard remon corner over 5/8" rerod.		
Found nail & tag #21273 East side power pole	N80°W	72.95 Feet
Northwest corner of storm sewer grate	S85°E	16.72 Feet
Northwest corner telephone riser box	S35°E	87.93 Feet
West leg stop sign	N40°E	46.68 Feet
A05 T9N-R2W	NORTH	99.00 Feet

OF MICHIGAN WILLIAM G TINGLEY ROFFSSIONAL SUL. EYOR NO 30104 POFESSION

William Tir 11, 1000 Chairman

Surveyor's Michigan License No

County State Trunkline M-57, Page 32.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 ROCESSING MARCH, 1993

