

GRATIOT
CO

SEC 25, T9N, R3W

FROM JAN 1884 SURVEY BY R. J. FRAKER

- K-10 IRON POST COR. 1/2 AXLE - POSTS E. AND W. 50
- K-11 OAK POST + STONES - OAK 8" S75°E 1.24 - LYNN 11" S10 1/2°W 76 o.c.
- L-9 OLD STONE COR. COVERED BY BLUE STONE
- L-10 RESET BY PINE POST 4x4 - ASH 7" S-W 46 1/2 - WALNUT 8" NW 56 3/4
- L-11 BUGGY AXLE COR - 39.10 CHS W. FROM S.E. COR. 3

COR # 1/8 CORNERS

- 3 - IRON POST COR. 1/2 AXLE S. ELM 10 N. 88 1/2°E 76 HICKORY 8 N64W 65
- 4 - OAK POST ELM 10 S. 31 E. 35 OAK 16 S 75 1/2°W 35 1/2
- 5 - OAK POST RESET SUGAR 10 S22E 49 FENCE POST W38 - E 43 - 32
- 6 - OAK POST - NO. B.
- 8 - ASH POST - SUGAR 10 N78 1/2°E 24 S. ELM 6 N37 1/2°E 8 1/2
- 9 - OAK POST W. OAK 40 S. 42 E 40 BUTTERNUT 10 N68W 21 1/2
- 10 - STAKE S. ELM 17 S62W 61 1/2 NEW COR.
- 11 - OAK POST W. OAK 10 S. 58 1/2°E 34 1/2 POPLAR 8 S45W 4 1/2
- 12 - SET PINE ROOT 4x4 + STONES ELM 14 N33W. 67 1/2
- 13 - SET BUGGY AXLE AT DIST. AND 14 N OF RIVER BANK
- 16 - 2" GAS PIPE 5' 9" LONG AT COR