FEB 2 2 1996

For corners in

Gratiot

GRATIOT COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Located In:

Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

GRATIOT CO. MICH. RECORDED

'95 DEC 20 PM 1 28

net M. Dow REGISTER OF DEEDS

(County) North Star Township A-3, W. Bndry T_10 NR 2W 1. Public Land Survey Sec 6 2. Property Controlling in Section T Register of Deeds Stamp & File Number 3. Miscellaneous Property in Sec. _, Recorded Plat J K L М H I В D 5. Private Claims 2 5 Δ ۸. 3 4 ..7.. -8 0 Ю 12 a field survey on July 13, 1994 5 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 18 15 14 13 6 17 16 current manual of survey instructions of the United States Department of the Interior, Bureau of Land 7 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 19 20 24 8 Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 0 27 25 10 30 29 28 26 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 35 12 31 32 33 34 36 13 Description of original monument and accessories and/or subsequent restoration: ACCEPTED BY THE GRATIOT COUNTY SURVEY PEER **GLO Notes** GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN 1852. Resurvey of 10-2 PUBLIC ACT 345 OF 1990 AT A MEETING HELD /1 29 95 Austin Burt, Deputy Surveyor S89°50'W Random between Section 6 and 7 71.74 chains intersect West boundary 8 links South of Corner NGT N89°43'E corrected between 6 and 7 William Tingley, PS, Chairman Old Bearing Sugar 12" S67°E 41 links Old Bearing Sugar 14" N37°E 37 links 1871, D.W. Altenburg, County Surveyor, Liber B, Page 47, Record of Minutes of Survey Post 3" x 3", old section corner found Elm 6" S46-3/4°E 86 links White Oak 3" N47-1/2°E 105 links 1967, Merril Hunter, Job No. E-107 and E-107A Found corner 9.24 feet North of Southeast Corner, Section 1, T10N-R3W B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1" Iron Pipe 1.65 feet long in Monument Box 9.68 feet North of Southeast corner Section 1, 10-3 Below Iron pipe found a large (10 pound) pointed stone. Below stone 2.4 feet deep found a 3/4" Iron Pipe driven into wood stake. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Remonumentation Corner in Monument Box over 1" iron Pipe Set Nail and Tag in 6" Elm 76.2 feet N52°E Found Nail and Tag in Power Pole S45°E 65.11 fee 文 4 Found Nail and Tag in Power Pole S30°W 94.40 feet Found Nail and Tag in Power Pole N40°W 51.67 feet This corner is accepted as a careful and faithful perpetuation of the position of the original corner. Surveyor's Michigan License No. _ 30104 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1976 REVISED JAIN, 1983 ADAPTED FOR WORD PROCESSING MARCH, 1983