

LAND CORNER RECORD

				_	Houghton		co	COUNTY	
				T	• _	51N	R3	5W	
DESCRIPTION OF CORNER Se	ection Corn	er 20,	21, 28	, and	29				
CORNER MONUMENT 1" 1.D. >	k 18" iron p	pipe wi	th 4" a	lumin	um c	ар			
DATE MONUMENT PLACED AND WIT	TNESSED	June 1	, 1972						
WITNESSES TO CORNER	Ash 7	S14°W	(mag.)	82.7	ft.	"S29, N	BT"		
N -	Power Pole	n64°e	(mag.)	57.5	ft.				
20						to si	lde of P	ole)	
AN	4D							-	
CIRCLE CORNER REGISTERED								 _	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner had been restored by B. D. Buckler, R.L.S., on June 6, 1966, by reference to old fences and a county road centerline, as follows: "This corner placed midway between two old fence lines, 25' north of fence line and in line with fence to north. Corner lies 27.5' west of a fence line running approximately south." For a monument, Buckler drove a 1½"x30" iron pipe into the road. Buckler's monument apparently was heaved by frost and torn out by a road grader. Position located according to Buckler's record and a new monument installed.

SURVEYOR'	S	SEAL
-----------	---	------

SIGNED

REGISTERED LAND SURVEYOR
Arthur O. Enger

DATE August 21, 1972

DISTRIBUTION:

District Surveyor

Forestry Division, Lansing

Area Forester

R 4047 Rev. 1/72