Cons. 4047

MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_51 NR 36-37.W

	Houghton	_ COUNTY
DESCRIPTION OF CORNER	Sec. corner for sections 18, 19, 13,	24
DESCRIPTION OF CORNER	MONUMENT_1" pipe with 4" brass cap	
WITNESSES TO CORNER .	2-3-58	
	16" hard maple 41°, E 60 links. Marked	"S18MET"
	_ 14"_hard_maple_N 27°. N 45 linksMarke	d "S13NBT"
	11" hard maple, S 26°, W 60 links. Mark	red_"S24NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR

RESTORED. Replaced from two probable B. T.'s. Maple stump bearing S 3°, W 21 links. Stump recently cut, bottom of scar visible in wood. Maple bearing S 35°, E 29 links. Tree green but rotted inside; has been chopped out many years ago. Numerous blazes in vicinity. Position checks with streams to north.

SURVEYORS SEAL

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE 5-1-59