Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner placed at 2 old wood posts with a cedar stump bearing S30°E, 25 links. Stump in poor condition. Found an old turnout in proper position for hemlock B.T. Found Cedar line tree 1.48 chs North of corner to correspond with record field notes.

SURVEYOR'S SEAL

CIRCLE COMMER REGISTERED

REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE April 24, 1963