SURVEY-& REMONUMENTATION

F.A. 345 OF 1990
Houghton County
\times \times \times \times \times \times \times \times \times
ortcorners in DEZ. O. 1997

APPROVED LAMD CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JAN 0 9 1998

H

For corners in DEZ. O. C	997		ı					
Houghton (County)	Located In:	Corner Code #		OUNT		Ņ	11:8	2 6
Public Land Survey	T <u>52N</u> R <u>34W</u> T R T R	M-5 *	- LC -	3/ 465	PAU Fee: Page	1. c		. ØØ 2
 Property Controlling in Section Miscellaneous Property in Sec. 	TR STR STR STR		-	Registe	r of Deeds Sta	amp&	File Nu	mber
	corded Plat			1 A B C	b E F G	_HI	i J K	L I
that under requirements of P.A. above were in conformance w survey instructions of the Unite decree of a Court of Law and conformance with the rules of testablished, re-established, more NOTE: Not more than 2 conformance with the rules of the	, in a field survey on <u>20 Nove</u> . 74, Michigan P.A. of 1970, the cornition regulations and rules therefore a sed States Department of the Interior, for that the corner points mentioned the Michigan Board of Land Surveyor numented, recovered, found as expresented, all in the same town and remonument and accessories and/or monument and accessories and/or monument to Sections 12 and on.	ner points mentioned in as required in the curre Bureau of Land Manag d in lines 3, 4 and 5 are sor by a Decree of a seed below: range, may be recorded as the corded are subsequent restor or subsequent restor	a lines 1 and 2 ent manual of ement or by a above were in Court of Law; ded ation:	2		-15	2	12
B. Description of corner e	vidence found and/or method ap	polied in restoring or	reestablishing	corner:				
M-5; Section Corner co	ommon to Sections 12 and	d 13, T52N, R34	w;					
intersection of th x 36" galvanized	B" iron rod set over a 1" x ne centerlines of Askel Roa iron pipe with cap set insi f the original corner.	d and Tower Ro	ad. Replac	ed found n	nonuments	with a	a 1" (1	.D.)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5; Section Corner common to Sections 12 and 13, T52N, R34W;

Set a 1" (I.D.) x 36" galvanized iron pipe with cap inside a cast iron monument box.

Set 7" spike	NW/side	6' Cedar Fence Corner	N61°E	38.42'
Set 7" spike	SW/side	8" Aspen	S36°E	55.71'
Set 7" spike	NW/side	5" Red Maple	S30°W	139.82
Set 7" spike		6" White Birch	S47°W	108.29'
Set 7" spike		Power Pole	S59°W	63.67'
Set 7" spike		6" Red Maple	N29°W	156.18'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

*This corner is also A-5 of T52N, R33W.

MICHAEL

MILESKI

PROFESSIONAL

SURVEYOR

No.

39091

Signed by	Date 11 Dec 1997
Surveyor's Michigan License No. 39091	

A. Description of original monument and accessories and/or subsequent restoration:

M-5; Section Corner common to Sections 12 and 13, T52N, R34W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Yellow Birch

14

N39°W

25 lks.

and a

Hemlock

30

N69°E

17 lks.

During the subdivision of T52N, R33W, by William Burt, D.S. in 1849, this corner was further witnessed by a

Hemlock

30

N65°E

17 lks.

and a

Sugar

7

S53°E

62 lks.

This corner was reestablished on 13 April 1973 by Arthur Enger, P.S. #13581 "at intersection of approximate construction centerlines of a N & S county road and a county road going W, which are presumed to be the section lines by common report". According to a Land Corner Recordation Certificate prepared by Mr. Enger dated 28 December 1973 and recorded in Liber 1 on page 123 of the Baraga County Land Corner Records, this corner was monumented with a 1" (I.D.) x 24" iron pipe with 4" aluminum cap witnessed by a

Nail in Power Pole

S62°W (mag.)

66.19

Stop Sign Post

S16°E (mag.)

44.3'

Telephone Jct. Box

N36°W (mag.)

94.0'

Top Jot Ca

Silvery Athan Mark