LAND CORNER RECORDATION CERTIFICATE

F	Filin	g Requirement of	Act 74, Mich. P.	.A. 1970	_							
For corners in												
Houghton (County)	Located In:	Corner Code #	ŧ									
Public Land Survey	TR_ TR_ TR_											
Property Controlling in Section	TR_ S_15T_52N_R_ S_15T_52N_R_											
3. Miscellaneous	S TR_											
Property in Sec.	S TR_				Re	gister	of De	eds St	amp &	File	Nun	nber
4.1441-				•								
4. Lot No, Recor	ded Plat			,	A E	3 C	D E	FG	н	1	JΚ	LN
	4	Aug 26 1999			2	6——	- 5	_4_	3_			_ _
	5	Aug 25 1999		:	3		11	\perp	_ -	لـــا		_Ī_
I, Stephan J. Szyszkoski	, in a field survey on _	, 19	do hereby state that u	under 4	• 	-	-		<u></u> 10	1-1	1—	-12
requirements of P.A. 74, Michiga conformance with regulations and	rules therefore as require	d in the current manual o	of survey instructions	of the	;					-		-
United States Department of the I that the corner points mentioned	nterior, Bureau of Land M	anagement or by a decre	e of a Court of Law ar	nd /or a	5	8	-17	-16	1,5	-1	4—	13
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court of	Law; established, re-	established, monume	ented,	'⊢		+	+		\vdash	-	
•				6	i i	9——	-20	-21 	2 ['] 2	-2	3—	2'4
NOTE: Not more than 2 com on this certificate.	ers, all in the same towr	n and range, may be r	ecorded	9			29					
on and continues.				_	0 <u></u> 3		29	-28-			6	25 _
				1	23	1	32	_33	3 4 _	3	5	36
				1	لـــاء		1_1			Ш		
(4-Sec. 15) Northwest 1/16 cor	ner, Section 15. Co	rner not estabilshe	o in the original	survey.	roun	a no s	subseq	uent r	ecora.			
B. Description of corner evid) monument, at record	bearing and distant	ce from the 1980 a	accessori	es an	d det	ermine	d that	it was	s pla	aced	at
an erroneous position about 46 established the corner midway the position for the corner, 1 (4-Sec. 15) Found no evidence lines connecting opposite 1/16 aluminum MDNR tablet, appropri	and on a straight lived placed a 1" ID x 32 of prior monumentation corners. At the pos	ne between Quarter (" iron pipe capped (on at the corner po	corner 1295.91' no with a 4" dia. cas sition. Establish	orth and s st alumin hed the c	Cente um MD orner	r of S NR tal at ti	Section blet, he int	n 1295 approp ersect:	.91'so riately ion of	outh. y sta stra	. At amped aight	: ! .
5" Y. Birch S22E 7.2' 5" Y. Birch MB5M 3.9' 5" Sugar N46M 20.2'	ap. (4) Ing: Bla 6S BT" 8" 5 do 7" 5 do 6" 6 do 6" 6 cces are to Bea	ries established to pe Set 1" pipe with 4 zed and scribed the Sugar N2BW 13.95' Sugar N86E 15.0' 7.Birch S25W 31.7' Maple N74W 5.65' rings are magnetic. ch in lower blaze.	following: "1/16S BT" do do do	The state of the s		STEPI SZYSZ LA SURV	HAN KOSI ND YEYOF	1	THE REPORT OF THE PARTY OF THE			
Signed by Surveyor's Michigan License N	I. Smpykva 103392	h	Date	10	0/19	199	9					