Cons. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 52N N.R. 35W

			Houghton	COUNTY
DESCRIPTION OF CORNER _	‡ corner be	etween sections 34-	-35	
CORNER MONUMENT	l" pipe wi	th 4" aluminum cap.		
DATE MONUMENT PLACED AN	D WITNESSED _	6 - 19 -62		
WITNESSES TO CORNER	•••	18" Cedar (¿5 NBT)	м81 ⁰ E, 33 links	
N35		9" Soft Kaple (201	MBT) N33 ⁰ W, 93 links	
CIRCLE CORNER REGISTERE	AND			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner replaced at 12" iron pipe set by unknown surveyor. Found 14" Cedar stump bearing S50°E (scribed 2.8) Mile is short; ‡ corner appears to have been set midway.

SURVEYOR'S SEAL

SIGNED Silly D Sucklin DATE PEARCH 7, 1963

Billy D. Buckler