LAND CORNER RECORDATION CERTIFICATE

F	Filing	Requirement of Act 74, Mich	n. P.A. 1970			
For corners in			1			•
Koughton	Located In:	Corner Code #				
(County)			İ			
1. Public Land Survey	T ^{52H} R 36 T R T R	LINE TREE 19-J9				
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR			Register of De	eds Stamp 8	& File Number
4 Lathia Book			•			
4. Lot No, Recon	ded Plat		, 1	ABCDE	FGH	IJKL
o. i iivato ciamis	······································		1	<u>i</u> i i i		
	Na	ıy 21 1998	3		— 1 — 1 – 3 –	T-1-1-
į Stephan J. Szyszkoski		, 19 do hereby state				
requirements of r.A. 74, Michiga	n P.A. of 1970, the comer p	points mentioned in lines 1 and 2 abo	ve were in	-/	— 9——10— 	11-12-
conformance with regulations and	rules therefore as required in	n the current manual of survey instruct agement or by a decree of a Court of L	ions of the			
that the corner points mentioned	In lines 3, 4 and 5 above wer	re in conformance with the rules of the	Michigan	—1 8 -17 	1615	14-13-
Board of Land Surveyors or by recovered, found as expressed be	a Decree of a Court of Li	aw; established, re-established, mo				
•			8	—19——20——	2122-	23-24-
	ers, all in the same town a	nd range, may be recorded	9	- - - -		
on this certificate.			10	-30 -29	2 8 27-	26- 25-
			11		 	+
			12	-3132-	_3334_	35 36-
Line Tree between 19 and J9 on West Corrected between Sec. 23 Set I.Pipe for cor found so swamp".	and 26 67.62 Ceda	r 12, 79.99 Sec. Cor." Melvin	C. Larsen, in	1961, states	in notes for	corner I9 "
		od applied in restoring or reestabl				
Recovered a hollowed, burned or notes. No markings were found confirm that this is the tree I the record. Distance west to a difference not being unusual in location, I place, in the cente stamped "MICH DNR PS 33986".	on the cedar but they we have referred to in his no monument at I9 also che no this township. I accord to the tree, which is	would most likely have been bu otes. There are no other ceda cks with the record. Distance ept this tree as the original s hollow to ground level, a 1"	rnt away. By a rs nearby. Dis east to remon line tree marks ID x 32" iron	measurement to stance west to umented K9 is ed by Higgins. pipe capped w	Larsen's pi swamp edge 69.42 ch., t To preserv	pe at I9, I checks with the this
"MICH DNR PS 33986". Blazed at the following: 10" Y. Birch S66E 20.25' "E 6" Maple S19W 19.35' 8" Cedar N18W 45.80' 5" Hemlock N50E 31.65' Distances are to notch in lower Squared a 10" Balsam S80W 1.6' of tree. Bearings are magnetic	c cap nd scribed LT BT" do do do r blaze. to center	es established to perpetuate locati	The state of the s	STEPHAN J. SZYSZKOSKI LAND SURVEYOR NO. 33986	** ***	
Simulation 1+21	100	<i>V.</i> /·	1.	1.90		

Surveyor's Michigan License No. For the Michigan Department of Natural Resources - Forest Management Division

33986

T52N-R36W Corner I9 Section corner common to Sections 22-23-26-27. Field survey date May 21, 1998

Part A Continued from the front:

1961 notes by Melvin C.Larsen, in a retracement of the lines between 22-23 and 26-27: "From the M.C. Cor on the south shore of Lake Roland...run due south magnetic and chained 1.90 I.pipe app. 16' west (old)...33.50 Set temp stake. Set I.Pipe for Cor [22-23-26-27] 42' east. Found some old blazes N&S. checks with calls to swamp 7 ch. east and a cedar possible line tree and east over swamp. NBT maple 8" N48W 12.3', NBT Birch 10" N82E 13.3'"

Part B Continued from the front:

These facts refute the assertion that the 1994 monument represents the position - even approximately - of the original corner. I accept the pipe recorded in 1984 as the best available evidence of the position of the original corner. At the position of the 1" pipe I place a 1" ID iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. The monument was placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.