LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement of A	ct 74, Mich. P.A. 1970
Howahton	
Located In: Corner Code #	
1. Public Land Survey	
7 R	_
3. Miscellaneous S T R	Register of Deeds Stamp & File Number
4 Lable Break (Bla)	
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKLM
15 May 26 1998	2 6 5 4 3 2 1 1
J8 May 19 1998	3
I, Stephan J. Szyszkoski , in a field survey on, 19do	o hereby state that under 4 7 8 9 10 11 12-
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines conformance with regulations and rules therefore as required in the current manual of s	s 1 and 2 above were in
United States Department of the Interior, Bureau of Land Management or by a decree of	of a Court of Law and /or 6 19 17 16 15 14 13
that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established,	
recovered, found as expressed below:	8 19 20 21 22 8 24
NOTE: Not more than 2 corners, all in the same town and range, may be reco	corded 9
on this certificate.	10 30 29 28 27 26 25
	11
	12 31 32 33 34 35 36
607.14'. 1981 measurement west to 1/4 by H. Lawrence O'Donnell, RLS is "Maple, S24E 11.1' 12" Y. Birch, NB2E 13.1' 18" Maple. 15-Sec. 23) West 1/16 corner between Sections 23-26. Corner not estab	
B. Description of corner evidence found and/or method applied in restoring 18) Found a 2" iron pipe at record bearing and distance from the 1979 easurements show that this pipe is 0.7' North and 5.2' West of the intistance west to the quarter corner to be 2606.60'. I accept the pipe orner. At the position of the found pipe and the corner, I place a 1" ablet, appropriately stamped. Corner placed and witnessed by D.Lampel	N40M 9° maple witness by R.A. Mick, in good condition. My tersection of straight lines between quarter corners. I find the as a careful and faithful determination of the position for the "ID x 32" iron pipe capped with a 4" dia. cast aluminum MDNR
15-Sec. 23) Found no evidence of prior monumentation at the corner pos earing between Section corner 1343.35° west and Quarter corner 1343.35 ron pipe capped with a yellow plastic cap which is stamped " MICH DNR araga District Office.	sition. Established the corner midway and on a line of mean true of east. At the position for the corner I placed a 1° ID x 32° PS 33986°. Placed and witnessed by D.Lampela and B.Wheeler,
C. Description of monument for corner and accessories established to perp J8) Set 1" pipe with 4" MDNR cap. (15) Set 1" pipe with ye lazed and scribed the following: cap. Blazed and scribed 0" Sugar S02N 5.5' "C1/4 BT" 14" Double Sugar N46E 14" Sugar N67E 7.55' do 6" Triple Sugar S29E 21.	allow plastic of M/C///of the following:

33986

Surveyor's Michigan License No.