## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Houghton	Located In:	Corner Code #											
(County)													
1. Public Land Survey	T 52N R T 52N R T R	36N A7 36A 85											
Property Controlling in Section     Miscellaneous Property in Sec.	S TR_ S TR_ S TR_			Reg	ister	of I	Deeds	: Sta	mp &	i Fil	e Nu	mbe	<u></u>
4. Lot No, Reco	rded Plat			<b>.</b> .	_			· с	U		• •		
5. Private Claims			1 2		Ť	- 5-	Ť	Ť	- <del> </del>   -     -	İ	Ĭ	Ţ	
requirements of P.A. 74, Michig	an P.A. of 1970, the come	October 18 1995 to hereby state to points mentioned in lines 1 and 2 above	e were in _			- 8 -		,	-10- 	-	11-	   12   1	
United States Department of the that the corner points mentioned	interior, Bureau of Land Mi d in lines 3, 4 and 5 above v	d in the current menuel of survey instruction enegement or by a decree of a Court of La were in conformence with the rules of the fill Lawr, established, re-established, mon	wand for 6 Michigan	18 		12-	10	+	 -15-		14	_13	-
recovered, found se expressed b		- , , ,,	. 8	19	+	-20-	┼╬	+	-2 2-	+	23_	_2 4	-

A) Description of original monument and accessories and/or subsequent restoration:
(A7) Corner coason to Sections 18-19 152N-R3oN and Sections 13-24 152N-R37N. Corner established in 1845 by Nm. A. Burt. "80.00 Corner of Sections 13824 and set post. Sugar 10 S39N 61, do 12 N37N 28". Corner noted in Mead records as 1 1/2" iron pipe found January 24, 1966 with the following witnesses: 7" Elm (C&H tag) 7" Hard Maple (Yellow tag). Found no subsequent record.

(85) Quarter corner common to Sections 7-18. Corner remonumented in 1964 by Billy D. Buckler, RLS at location of a mood post placed by Copper Range Company. Corner monumented by a 1° iron pipe with 4° aluminum cap and the following NBTs: 7° H. Maple S25E 36.5 links, 6° Ironwood M47W 24.5 links.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

on this certificate.

(A7) Original post and accessories not recovered. Recovered a 1 1/2° iron pipe with 8° Sugar Maple and yellow Vulcan tag facing. The 7° elm with C&H tag noted in 1966 is dead and has recently fallen. Distance north 1/2 mile to probable original 1/4 corner and 1 mile to original section corner check reasonably well with the original record. I accepted the pipe as the best available evidence of the position of the original corner. Left the pipe in place and marked 4 witnesses as described below.

(85) Found and accepted Buckler's monument, as described, in good condition, and at record bearing and distance from his 1964 MBTs. Left the monument in place and marked three new mitnesses as described below. Distance west to original corner is about .5 ch longer than record - an index error found to be common in this area of the township. Also, distance to streams 11.6 ch. and 22.6 ch. east check with the original record.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(A7) Found 1 1/2° iron pipe. Blazed and scribed the following new bearing trees: 9° Sugar found with Vulcan tag	(85) Found 1" iron pipe with 4" aluminum cap. Blazed and scribed the following new bearing trees: 7" Sugar N42E 28.0" "1/4S NBT"	STEPHAN SZYSZKOS
\$18W 7.0' "\$24 MBT"	14" Hemlock S65N 46.8' "1/45 NBT"	경* LAND
5" Sugar S48E 21.1' "S19 NBT"	9° Sugar SO4W 12.9' with Copper Range	SURVEYOR
10° Sugar N42E 20.9' "S18 NBT"	tag. Bearings are magnetic.	No.
12" Sugar N18N 26.4' "513 NBT"		33986
Bearings are magnetic.		AND SU
0 1 1		Salar Salar Salar

Signed by Stephen J. Syngholi

Date 10-26-95

Surveyor's Michigan License No. 33986

For the Michigan Department of Matural Resources - Forest Management Division