MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 53 NR34-35 W

		-	Houghton	COUNTY
DESCRIPTION	OF CORNER	Section corner	common to Sec. 1s 30-3	1-25-36
DESCRIPTION	OF CORNER	MONUMENT_1"	pipe with 4" brass c	ap
WITTNESSES	TO CORNER	7" Cedar	N 58°W ns-25-mbm	25 links
		9" Cedar	N 79° E	34 links
		8" Cedar	"S 30 NBT" S 1° E	8 links
			uVB4u	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from one cedar B.T. bearing S 35° W 8 links.

Tree cut down and in poor condition. Found cedar stump S 35° E 12 links.

Found cedar post in proper position. Corner lies in swampl

Found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED Silly D. Buckles DATE 8/28/57