DEC 1 6 1996

COMMISSION

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of 1-77 Filing Requirement of Act 74, Mich. P.A. 1970

| For Co | orners in | | | HONON GOUNTY RECORDED |
|--|--|---|---|--|
| | Huron | Located in: | Corner Code | # ' |
| | (County) | | Odiner Code | 30 OCT 96 9:47 A.M. |
| 1. Pu | blic Land survey | Grant T 15 N R 11 E T R T R | H-13 I-13 | FRANCES L. HOLDWICK REGISTER OF DEEDS |
| | operty Controlling Section | TR STR STR | | |
| 3. Mis | scellaneous | S T R | | Register of Deeds Stamp & File Number |
| 4. Lot | : No | , Recorded Plat | | A B C D E F G H J K L |
| do herebin lines 1 current r Manager above w Court of expessed NOTE: | es T. Meek by certify that under re I and 2 above were in nanual of survey instr ment or by a decree o ere in conformance w Law; established, re d below: Not more than a on this certifical escription of original survey South South & Corne Post Beech 20", N4 Hemlock 10", | , in a field survey onOctober 11 quirements of P.A. 74, Michigan P.A. of conformance with regulations and rules of fa Court of Law and/or that the corner po- lith the rules of the Michigan Board of Lan- established, monumented, re-monume 4 corners, all in the same town a fa. al monument and accessories and/ ch Bdy. T15NR11E, 1835, Har er of Section 34 5½°E, 30 links N82°W, 27 links rveyors record, recorded su | 1970, the corner pointhereof as required in of the Interior, Bureau ints mentioned in line of Surveyors or by a linted, recovered, found range, may be for subsequent reservey Parke, D. 1-13 | 2 6 5 4 3 2 1 1 3 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| B. Des | scription of corner | evidence found and/or method app | olied in restoring o | r reestablishing corner: |
| H-13 | South 1/2 Corne | r of Section 34 | I-13 | Corner of Sections 34 and 35 |
| | Found 1" iron 2" below grd. At centerline of Huron Line Rd. | | | Found 1%" pipe, 4" below grd. At intersection Huron Line Rd. and Hartsell Rd |
| | | he best available evidence orner position | | Accepted as the best available evidence of original corner position |
| | | | | |

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-13 South % Corner of Section 34

I-13 Corner of Sections 34 and 35

Set 1/4" iron w/cap #39089, 3" below grd. over 1" iron

At centerline of Huron Line Rd.

From which:

Nail in power pole bears S40°E, 81.7'

1/2" iron flush w/grd bears N52°E, 30.0'

%" iron flush w/grd bears N54°W, 30.0° %" iron flush w/grd bears S56°W, 25.0°

Set 1/2" iron with cap #39089, 3" below ground over 11/1" pipe

From which:

Nail in power pole bears N60°W, 83.3'

Road sign post bears N10°W, 33.3'

Road sign post bears S66°E, 95.9'

Buried Cable post bears South, 32.4'

1" pipe, 4" below grd. bears, East 49.1'

Signed by

Date

Surveyor's Michigan License No. 39089

APPROVED AT PEER BOARD MEETING.

CSG

GRANDER OF MICHOLINA 39089

......

LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983