OOT 2 9 1996

REMONUMENTATION Re-Man Liber 1, Page 15

BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

COMMISS			CORDATION CERT					
For corners in	F31.11	ng Keduitement	of Act 74, Mich. P.	4. 1970 				
Huron (County)	Located In:	Corner Code	e#					
1. Public Land Survey	T R T R	aris T <u>15NR14E</u>			STATE OF MICHIGAN HURON COUNTY RECORDED			
2. Property Controlling	TR S TR			-	10 SEP 96	8:41 A.M.	;	
in Section 3. Miscellaneous Property in Sec.	S IR S TR	!K			FRANCES L. HOLDWICK REGISTER OF DEEDS			
Property in Sec.	9		<del></del>	Regist	er of Deeds S	tamp & Fil	e Numbe	
4. Lot No, Rec	orded Plat				~ ~			
5. Private Claims	777 A 2 at			1 A B C		G H I	J K L	
				3	5	3-1-	2 - 1	
Charles S. Getz	in a field survey on	July 2 19 9	6 do hereby state that u	nder 4 7	    	10	1112	
requirements of P.A. 74, Mich conformance with regulations a	nd rules therefore as require	ed in the current manu	al of survey instructions of	fthe 5				
United States Department of the that the corner points mention	ed in lines 3, 4 and 5 above	were in conformance	with the rules of the Michi	lgan i	17-16-	15	14-13	
Board of Land Surveyors or recovered, found as expressed		of Law; established, i	re-established, monumen	ited, 819	_2021_		23 24	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				9			<u> </u>	
on this certificate.	,			10-30-	2928	27	2625	
				11				
				12 31	32 33	34	35 36	
A. Description of original m	nonument and accessori	ies and/or subsequ	ent restoration:					
A-13 GLO Notes In Set Post at Beech 11", S Do. 16", N	stersected Range 81.06 Chains 811°W, 14 Links 123-1/2°E 31 1/2		County Surve Act 132 - No by Huron Sur	ne, Unrecor	ded Surve	Act 7 y dated	4 - No 8-30-	
Beech 24", N	at 40.00 Chains 64°E, 25 Links 40°W, 35 Links	5	County Surve Act 132 - No	yor's Recor ne	d - None,	Act 74	- Non	
B. Description of corner e	vidence found and/or me	ethod applied in res	toring or reestablishing	corner:			•	
A-13								
Found 1/2" Ir	on 31, T15N-R14M on Bar in Center Intersection of na Road)	rline of		APPROVED P	eer board 7 8	MEETING , 1990		
B-13								
Found No Evident Straight line Section 31, T. C. Description of monument	ction 31, T15N-F ence of an Exist , using GLO prop 15N-R14E. It for corner and accesso	ing Corner a	PER SELIAN SA	otion 31 m	1 E X " TO 1 / TO .	2" Iron and SW (	Bar or Cor,	
A-13 SW Cor, Section 31 1/2" Iron Bar in G N45°E 70.75' to Na: S45°E 44.05' to Na: N45°W 72.47' to Na: S45°W 49.80' to Na: East 2716.65' to S	ravel Road Bed il in SE Side of il in NE Side of il in NE Side of il in SE Side of	Power Pole Power Pole Anchor Pole	North 36.05'	in Gravel I to 1/2" Iron to Nail in to Nail in to Nail in to Nail in	Road Bed  Bar in G  E. Side o  6" Willow  Clump of  Sec 31	f Fence Apple T	Post	
Signed by Charle	es 2, Ge	Allininining of	Mich/////Date	July 15,	1996			
Surveyor's Michigan License	No. 25843 <b>&lt;</b>	Charten						