SURVEY &	
REMONUMENTATION	

APR 27 1995

REMONUMENTATION

COMMISSION

Re-Mon. Lider 1, Page 1

AND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Huron		Located In:	Corner Code ≠#	
	(County)		555. 5535 =	
1.	Public Land Survey	T <u>15 NR 15 E</u>	A-1/3 A-2	
		T R		
		T R		
		T R		
2.	Property Controlling	S T R	· · · · · · · · · · · · · · · · · · ·	
	in Section	S T R		
3.	Miscellaneous	S R		
	Proporty in Soc	e t b		

STATE OF MICHIGAN HURON COUNTY RECORDED

1 NOV 94 3:45 P.H.

FRANCES L. HOLIWICK Register of Deeds Stamp & File Number

___ , Recorded Plat . 5. Private Claims

I Charles S. Getz in a field survey on August 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - Found Monu Box in Asphalt at Intersection of Helena Road and Finkle Road over former location of 3/4" Pin as recorded in Liber 3 of Surveys, Page 82, Huron County Records, said survey dated 10-25-76, by Huron Surveying, Inc.
 - Found 5/8" Bar in gravel road bed (Finkle Road). Raised with 1/2" Iron Bar. GLO Notes were researched. Huron County Road Commission notes & County Surveyor records show no evidence of Corner.

Approved at Peer Board Meeting,

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NW Cor, Section 6, T15N-R15E Found Mond Box

A-2W 1/4 Cor, Section 6, T15N-R15E Found 5/8" Iron Bar



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NW Cor, Section 6, T15N-R15E Monu Box N35°E 89.25' to Spike in Brace Pole N45°W 71.95' to Spike in Power Pole N45 W /1.95 to Spike in rower role S45°W 66.66' to Spike in Power Pole S45°E 64.75' to Spike in GTE Box Post South 2693.94' to W 1/4 Cor, Section 6, T15N-R15E

W 1/4 Cor, Section 6, T15N-R15E 1/2" Iron Bar East 4.0' to Centerline of Gravel Road S85°E 47.65' to Spike in Power Pole S45°W 40.30' to Notch in North End of 48" CMP S30°W 67.50' to Notch in South End of 48" CMP North 2693.94' to NW Cor, Section 6, T15N-R15E. South 2632.04 to SW Cor; Section 6, T15N-R15E

Signed by _	Charles	S.	Gets
	lichigan License No.		25843

August 30, 1994 ____ Date _