## SURVEY & REMONUMENTATION

APR 27 1995

REMONUMENTATION COMMISSION

Property in Sec.

Re- Man. Leder 1, Page 2 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

HURON COUNTY RECORDED

For corners in

Huron Located In: Corner Code ≠# T 15 NR 15 E 1. Public Land Survey R 2. Property Controlling \_ R \_ \_ T \_ in Section Miscellaneous

1 NOV 94 3:45 P.H.

FRANCES L. HOLDWICK REGISTER OF DEEDS

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_ Private Claims \_\_

I. Charles S. Getz , in a field survey on August 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- Description of original monument and accessories and/or subsequent restoration:
  - Found 1" Iron Bar in Gravel Road Bed at Intersection of Purdy Road and Finkle Road as per Huron County Road Commission notes: Raised with 1/2" Iron Bar.
  - Found 3/4" Iron Bar in Gravel Road Bed (Finkle Road) as per Huron County Road Commission notes.

Approved at Peer Board Meeting,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

NW Cor, Section 7, T15N-R15E Found 1" Iron Bar

W 1/4 Cor, Section 7, T15N-R15E Found 3/4" Iron Bar



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

NW Cor, Section 7, T15N-R15E 1/2" Iron Bar N45°E 72.50' to Spike in Power Pole N30°W 82.30' to Southeast Corner of Retainer Wall
N45°W 117.40' to Southeast Corner of Barn
S45°E 43.00' to Notch in East End of 48" CMP
North 2632.04' to W 1/4 Cor, Section 6; T15N-R15E South 2638.75' to W 1/4 Cor, Section 7, T15N-R15E

A-4
W 1/4 Cor, Section 7, T15N-R15E
3/4" Iron Bar
East 7.0' to Centerline of Gravel Road
West 22.50' to Spike in 15" Ash Tree
N15°W 64.40' to Spike in Tripple Ash Tree
S15°W 35.80' to Spike in Double Ash Tree
North 2638.75' to NW Cor; Section 7, T15N-R15E South 2635.29 to SW Cor; Section 7; T15N-R15E

Signed by Charles	\$.	Hetz
Suprevor's Michigan License No.		25843

Surveyor's Michigan License No. \_\_\_

Date August 30, 1994