SURVEY & REMONUMENTATION

REMONUMENJANON2 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Re-Mon ation certificate	/	Page 116
t 74. Mich. P.A. 1970		0

For Co	rners in SECTION Huron (County) Located in:	Corner Code #	HURON COUNTY		
1 Dui	blic Land survey Oliver T16 N R 11 E	J-13	RECORDED		
1. Pu	blic Land survey Oliver T <u>16 N</u> R <u>11 E</u> (TR	K-13			
		_K-13	9 DEC 97 11:11 A.M.		
	ТR ТR	 	FRANCES L. HOLDWICK		
2 Dr	operty Controlling S T R		REGISTER OF DEEDS		
	Section S T R		VEGIBLEY OF DECID		
	scellaneous S T R		Register of Deeds Stamp & File Number		
O. IVIIC	, solidilodd				
	No, Recorded Plat				
5. Pri	vate Claims		2 6 5 5 4 4 3 3 2 4 1		
			3		
l. Jame	es T. Meek, in a field survey on _October 30		19 97		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned					
in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the					
current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
	ment or by a decree of a Court of Law and/or that the corner point ere in conformance with the rules of the Michigan Board of Land \$				
	Law; established, re-established, monumented, re-monumente				
expesse		,	10 30 29 28 27 26 25		
			11		
NOTE:	Not more than 4 corners, all in the same town and	d range, may be	recorded		
	on this certificate.				
			13		
A. Description of original monument and accessories and/or subsequent restoration: Original Survey South Bdy. T16NR11E, 1835, Harvey Parke, D.S.					
J-13	South 4 Corner of Section 35	K-13	Corner of Sections 35 and 36		
0 13	Post	K-13	Post		
	W. Ash 11", N47°W, 10 links		Aspen 9", N84½°E, 28 links		
	Cedar 6", N84°E, 21½ links		Cedar 9", N9°W, 1 links		
	Country approved a page of a page				
	County surveyors record: none Recorded surveys: L1, P347 LCRC: none		County surveyors record: none Recorded surveys: L3, P362 LCRC: none		
B. De	scription of corner evidence found and/or method appli	ed in restorina or	r reestablishing corner:		
	т.				
J-13	South 4 Corner of Section 35	K-13	Corner of Sections 35 and 36		
	Found 1" iron 4' South of centerline Kilmanagh Rd. Occupation line bears North		There is no remaining evidence of the original corner position.		
	Accepted as the best available evidence of the original corner position.				
	of the original corner position.				
C De	scription of monument for corner and accessories estat	hlished to perpet	usts locating the necition of the corner		
		to perpett	and issuing the position of the corner.		
J-13	South 4 Corner of Section 35	K-13	Corner of Sections 35 and 36		
	Set 1/2" iron with cap #39089, 2" below gr	rd.,	At proportionate distance		
	over iron		Set '%" iron w/cap #39089 2" below grd.		
	7		2' South of int Kilmanagh & Moore Rds.		
	From which: Tag in 6" sq. post bears N11°E, 34.65'		From which: Telephone box bears N33°E, 67.1'		
	Tag in PP bears S57°E, 84.5'		East leg of dirct. sign bears South, 14.4'		
	Tag in 8" Elm bears \$74°W, 78.4'		Road sign post bears \$37°W, 32.0'		
	1" iron bears West, 23.15'		Road sign post bears N18°W, 60.5'		
			'' iron bears \$38°W, 39.6'		
) .		WHILE OF MICHAIL		
			Marie Commence of Carling		
Signed I	y to the	Da	ate SO / PAMES I 9 7		
0	de Michigan Lineau No.				
SURVEYOR'S MICHIGAN LICENSE NO. 39089 FORMAP TO VELOCITY FOR A PROVED BY MICHIGAN BRARD OF LAND SURVEYORS, JAN 28, 1971					
APPROVED AT PEER BOARD MEETING, NOU 25 1997 REVISED MAY 14, 1975 REVISED MAY 14, 1975 REVISED MAY 14, 1975 REVISED MAY 14, 1975					
	,		LAND SURMININ		
			"THE HELLING!"		