SURVEY & REMONUMENTATION

JAN 2 2 1998

SECTION

Surveyor's Michigan License No._ PEER GROUP APPROVED AT

MEETING NOVEMBER

Re Man Lider 1, Page 69

LAND CO	RNER RECORDATION CER	RTIFICATE V
For corners in	equirement of Act 74, Mich. I	P.A. 1970
Huron Located In:	Corner Code #	
1. Public Land Survey Sand BeachT16N R 15E T R T R	H-13	STATE OF NICHIGAN HURON COUNTY RECORDED
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R		6 NOV 97 10:25 A.M. FRANCES L. HOLDWICK
Property in Sec. S TR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims		ABCDEFGHIJKLI
		2 5 4 3 2 1 -
I, <u>Charles S. Getz</u> , in a field survey on <u>Aug</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner point conformance with regulations and rules therefore as required in the United States Department of the Interior, Bureau of Land Manager that the corner points mentioned in lines 3, 4 and 5 above were in Board of Land Surveyors or by a Decree of a Court of Law; recovered, found as expressed below:	ts mentioned in lines 1 and 2 above vectors to the manual of survey instructions ment or by a decree of a Court of Law and conformance with the rules of the Mineral Court of the	t under 4 7 3 9 10 11 12 were in s of the and /or 6 18 17 16 15 14 13
NOTE: Not more than 2 corners, all in the same town and a on this certificate.	range, may be recorded	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
Description of original monument and accessories and	d/or subsequent restoration:	13
G-13 1834 G.L.O., H. Parke D.S. Set Post Cedar 20", East, 17 Links Birch 9", N73°W, 15 Links	Co. Surveyor Records - N Co. Rd. Comm. Records -	NONE, Survey Liber 2, Page 72 - Axle Axle - Certificate shows corner
H-13 1834 G.L.O., H. Parke D.S. Set quarter section post Hemlock 10", N86°E, 17½ Links Cedar 5", N69°W, 26 Links	Co. Rd. Comm. Records -	NONE, Survey Liber 2, Page 72 - 1" Pin in age 669 - Monument Box 1" Iron Pin in Post - Monument Box, L.C.R.C NONE
3. Description of corner evidence found and/or method a		
G-13 SW Cor, Section 34, T16N-R15E Found Axle Shaft in Monument Box Accepted as the best available evide of original corner position (Intersection of Helena & Buhl Roads	Found 1" Found 1" Found 1 Foun	, Section 34, T16N-R15E Pipe in Monument Box as the best available evidence al corner position
Description of manument for corner and accornation		
C. Description of monument for corner and accessories es G-13 SW Cor, Section 34, T16N-R15E Found Axle Shaft in Monument Box West 31.42' to 2" Pipe in Monument Box N60°W 93.95' to Nail in S. Side of Pox N30°W 64.02' to Nail in Anchor Pole N45°E 66.72' to Nail in NW Side of 18" N30°E 97.45' to Nail in NW Side of 30" West 2594.68' to S 1/4 Cor, Sec 33, East 2631.84' to S 1/4 Cor, Sec 34,	H-13 S 1/4 Co Found 1" West 19, Wer Pole N15°W 40 S15°W 57 Chestnut T16N-P15F West 263	the position of the corner: Or, Section 34, T16N-R15E Pipe in Monument Box 90' to PK Nail 0.83' to Spike in E. Side of Power Pole 90' to NE Corner of House 68' to Nail in N. Side of Power Pole 882' to SE Corner of Church 1.84' to SW Cor, Sec 34, T16N-R15E

Charles S. Getz Land Surveyor No. 25843

October 12, 1997