SURVEY & REMONUMENTATION

JAN 2 2 1998

SECTION

REMONUMENTATION Re Man Like 1, Page 69

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in							
Huron Located In: C	orner Code #						
1. Public Land Survey Sand BeachT16N R 15E			STATE OF MICHIGAN HURON COUNTY RECORDED				
2. Property Controlling in Section S T R 3. Miscellaneous Property in Sec. S T R		Re	-	OV 97 10: NCES L. H BISIESTAR	OLDWICK	Number	
4. Lot No, Recorded Plat		- A	B C D	E F G	н I J	KLM	
I. Charles S. Getz, in a field survey on Aug. requirements of P.A. 74, Michigan P.A. of 1970, the corner points conformance with regulations and rules therefore as required in the United States Department of the Interior, Bureau of Land Managem that the corner points mentioned in lines 3, 4 and 5 above were in Board of Land Surveyors or by a Decree of a Court of Law; recovered, found as expressed below:	17, 1997 do hereby states mentioned in lines 1 and 2 at current manual of survey instruent or by a decree of a Court of conformance with the rules of the conformance with the confor	ctions of the Law and /or 6 he Michigan	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	9-16-21-	-3 - 2 -10 - 1 -15 - 1 -22 - 2	1 12 12 13 13 13 13 13 13 13 13 13 13 13 13 13	
NOTE: Not more than 2 corners, all in the same town and non this certificate.	ange, may be recorded	9 10 11	30 29 31 32 32	28	-27 — 2 -34 — 3	536	
A. Description of original monument and accessories and G-13 1834 G.L.O., H. Parke D.S. Set Post Cedar 20", East, 17 Links Birch 9", N73°W, 15 Links H-13 1834 G.L.O., H. Parke D.S. Set quarter section post Hemlock 10", N86°E, 17½ Links	Co. Surveyor Records Co. Rd. Comm. Record Huron Surveying 5-2- L.C.R.C NONE Co. Surveyor Records post, Survey Liber Co. Rd. Comm. Record	- NONE, Sur s - Axle -90 - Certifi - NONE, Sur 3. Page 669 - N	vey Liber Ionument	ows cor 2, Page Box	ner		
Cedar 5", N69°W, 26 Links B. Description of corner evidence found and/or method a	Huron Surveying 10-		t Box,	L.C.R.C	NO	NE	
G-13 SW Cor, Section 34, T16N-R15E Found Axle Shaft in Monument Box Accepted as the best available evide of original corner position (Intersection of Helena & Buhl Roads	H-13 S 1/4 Found ence Accept of or	Cor, Section 1" Pipe in M ed as the be Iginal corner	onument st avail	Box .able e	vidence	e	
·							
C. Description of monument for corner and accessories e	stablished to perpetuate lo	cating the position o	f the corner				
G-13 SW Cor, Section 34, T16N-R15E Found Axle Shaft in Monument Box West 31.42' to 2" Pipe in Monument Bo N60°W 93.95' to Nail in S. Side of Po N30°W 64.02' to Nail in Anchor Pole N45°E 66.72' to Nail in NW Side of 18 N30°E 97.45' to Nail in NW Side of 30 West 2594.68' to S 1/4 Cor, Sec 33, East 2631.84' to S 1/4 Cor, Sec 34,	Four West West N15° S15° S15° S45° Chestnut N55° T16N-R15E West	A Cor, Section of Pipe in the 19.90' to Pipe in the 19.90' to Pipe in the 19.90' to Single Pipe in the	Monumer K Nail Spike in HE Corne Hail in l SE Corne SW Cor,	E. Side r of Ho N. Side r of Ch Sec 3	e of Pouse of Pow orch 4, Tl6	ver Pole N-R15E	

Surveyor's Michigan License No. PEER GROUP APPROVED AT Charles S. Getz Land Surveyor No. 25848 MEETING NOVEMBER

25843

PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983

October 12, 1997