Re-Man Leher 1, Page 198 LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN

For	Corners in			,		HURON COUNTY RECORDED				
	Huron (County)	Located in:	Corner Code #		mg = B	11 DEC 00	0.45	A M		
1. 1	Public Land survey	Fairhaven T 16 N R 9 E T R T R	D-13 RI	SUFFVE EMONUME 8 & N <del>AL</del>	NOTATION	FRANCES I REGISTER	L. HOLD	MICK		
	Property Controlling n Section	S T R S T R		SECTION	NO					
	Miscellaneous	STR			Register of Deeds Stamp & File Number					
5. F I, Ja do he in line currer Mana, above Court	emes T. Meek reby certify that under rec s 1 and 2 above were in a nt manual of survey instru gement or by a decree of were in conformance wit	, in a field survey on _October 30 quirements of P.A. 74, Michigan P.A. of 19 conformance with regulations and rules the actions of the United States Department of a Court of Law and/or that the corner poin the rules of the Michigan Board of Land established, monumented, re-monument	970, the corner points ereof as required in the f the Interior, Bureau ats mentioned in lines Surveyors or by a De	, 19 98, s mentioned he of Land 3, 4 and 5 excree of a	2 6 3 4 7 5 6 18 7 8 19 9 10 30 30 10	S D E F	G H	23	12 12 13 13	
	on this certificat				11   12   31   13   13   14   15   15   15   15   15   15   15	32 33	34	— 35 — 	36	
		l monument and accessories and/o th Bdy. T16NR9E, 1835, Har								
D-13	Post Burr Oak 12",	er of Section 32 N41°W, 44 links '8°E, 35 links		Corner of S Post Burr Oak 11 Pine 24", N	L", N72½°E,	111 link	s			

County surveyors record; none Recorded surveys: none

LCRC: none

1998 REMONUMENTATION

County surveyors record;  $\frac{1}{2}$ " iron Recorded surveys: L5, P55 LCRC: L1, P19

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South 4 Corner of Section 32

There is no remaining evidence of the original corner position. E-13 Corner of Sections 32 and 33

Found '4" iron in mon box At intersection of Kilmanagh & Rose Island Rds.

Accepted as the best available evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

**⊅-13** South 4 Corner of Section 32

> Set 1/2" iron w/cap #39089, at record distance.

From which:

Signed by

Tag in 14" Walnut bears N40°W, 35.8' 'iron 2" below grd. bears N60°E, 96.1' Spike in PP bears N88°W, 84.3' Drain leading to Saginaw Bay bears West, 100.04

E-13 Corner of Sections 32 and 33

15" iron in mon box

From which:

Road sign post bears N25°E, 49.3' Tag in power pole bears S24°E, 67.6' Road sign post bears \$72°W, 51.8' Telephone box bears N32°W, 71.1'

E OF MICH JAMES T. MEEK No.

TON COLAND STRUMENT

URVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No. <u>39089</u>

=APPROVED AT PEER BOARD MEETING. : // ー 24