1998 REMONUMENTATION

Surveyor's Michigan License No. _39089

APPROVED AT PEER BOARD MEETING, 11-24-98

Re- Man Liber! Page 184 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN

For C	Corners in							COUNTY IRDED	
	Huron (County)	Located	d in:	Corner Code	#		11 DEC 98	9:42 A N	
1. P	ublic Land survey	Т,	<u>17 n</u> R <u>10 E</u> R				FRANCES L	. HOLIWICK OF DEEDS	
ir	roperty Controlling Section fiscellaneous	ST ST	R R			Register of Do	eeds Stamp & Fi	le Number	
<i>a</i> 1	ot No	Pecorded Dist							
	rivate Claims					A B	CDEF	G H I J K	
						3 6 -	5 + 4 -	3 - 2	
					40.00	4 7 -	8 - 9 -	10 11	
do her n lines curren Manag above Court o expess	mes T. Meek eby certify that under re s 1 and 2 above were in t manual of survey instrument or by a decree of were in conformance w of Law; established, re sed below:	equirements of P.A. 74 conformance with requestions of the United f a Court of Law and/oith the rules of the Michestablished, monum	 Michigan P.A. of 19 gulations and rules the States Department of or that the corner poin chigan Board of Land lented, re-monument 	970, the corner point ereof as required in the Interior, Bureau ts mentioned in line Surveyors or by a D ed, recovered, four	s mentioned the of Land s 3, 4 and 5 ecree of a nd as	5 18 - 18 - 19 - 9 10 - 30 - 11	20 21		
NOTE	 Not more than on this certification 		he same town an	d range, may be	erecorded	12 31-	32 33	34 35	
۸ ۲	Description of origina	of manument and	necessaries and/o	r cubo cauant roc	toration	13		<u> </u>	
	inal Survey Sou								
J-13	South 4 Corner of Section 35 Post Hemlock 20", N81°E, 24½ links Hemlock 11", N28½°W, 10 links				13 Corner of Sections 35 and 36 Post Elm 22", N47°E, 31 links Beech 8", N32°W, 10 links				
	County surveyors record; iron pin Recorded surveys: L3, P61; L4, P763 LCRC: none				County surveyors record; none Recorded surveys: L1, P266; L4, P763 LCRC: none				
3. 🗆	escription of corner	evidence found a	nd/or method appli	ied in restoring o	r reestablisl	hing corner:			
г –13		er of Section		K-13		of Sections 3	35 and 36		
	There is no remaining evidence of the original corner position					" pipe in mor rsection of I		rm Rds.	
		PENC	NUMENTAT	ION		d as the best original corr			
		J	AN 28 1999						
			SECTION						
. D	escription of monur	nent for corner and	d accessories esta	blished to perpet	uate locatin	g the position of	the corner:		
-13	South 4 Corne	er of Section	35	K-13	Corner	of Sections 3	5 and 36		
	At proportion	nate distance			1" pipe	in mon box			
		Set ½" iron w/cap #39089 in mon box From which: Tag on power pole bears N56°E, 66.4' Tag on power pole bears N60°W, 63.8' Tag on power pole bears S50°W, 67.9' ½" iron in mon box bears East, 35.5'				on power pole bears N40°E, 62.15' d sign post bears S55°E, 64.55' t leg of direction sign bears South,			
	Tag on power Tag on power Tag on power				East led				
ianea	I by	lu		ת		L 8 0	ALC A	JAMES T. MEEK	