1998 REMONUMENTATION

Burveyor's Michigan License No. <u>39089</u>

APPROVED AT PEER BOARD MEETING, 11-24-98 PLB

LAND CORNER RECORDATION CERTIFICATE

STATE OF KICHIGAN

HUMBRIC COUNTY

HUMBRIC COUNTY

STATE OF KICHIGAN

HUMBRIC COUNTY

HURDN COUNTY

For Co	rners in			Í	RECORDED
<u> </u>	Huron	Located in:	Corner Code	# 62-6 5 mm / 10 mm / 10 mm	44 BCC 00 0-44 A W
	(County)		Exact Scan	SURVEY &	11 DEC 98 9:44 A.H.
1. Pul	blic Land survey	Fairhaven T 17 N R 9 E T R T R	_J-13 _K-13 ✓	MONUMENTATION JAN 2 8 1999	FRANCES L. HOLDWICK REGISTER OF DEEDS
	pperty Controlling	T R S T R S T R		SECTION	
3. Mis	scellaneous	s r R		Register of De	eds Stamp & File Number
4 lot	No	, Recorded Plat			
		11000100011101		A B	C D E F G H I J K L
do hereb in lines 1 current r Manager above w Court of expesses	by certify that under re and 2 above were in manual of survey instrument or by a decree of ere in conformance with Law; established, re d below:	, in a field survey on _October 30 quirements of P.A. 74, Michigan P.A. of 19 conformance with regulations and rules th uctions of the United States Department of a Court of Law and/or that the corner poir ith the rules of the Michigan Board of Land-established, monumented, re-monument 4 corners, all in the same town and the	970, the corner point ereof as required in I the Interior, Bureau ats mentioned in line Surveyors or by a E led, recovered, four	s mentioned the 6 18 18 18 19 19 19 11 11 11 18 18 18 18 19 19 19 11 11 11 11 11 11 11 11 11 11	
	on this certifica	ne.		13	
		al monument and accessories and/o uth Bdy. T17NR9E, 1835, Haz			
J-13	Meander Corner of Section 35 K-13 Post		Corner of Sections 35 and 36 Post		
	W. Ash 11", N1°E, 1.67 chains Willow 7", S86°E, 3.6 chains			Sugar 9", N64°W, 4 links B. Ash 8", N55°E, 38½ links	
	County surveyors record; none Recorded surveys: none LCRC: none			County surveyors record; none Recorded surveys: none LCRC: none	
B. De	scription of corner	evidence found and/or method app	lied in restoring o	r reestablishing corner:	
J-13	Meander Corn	er of Section 35	K-13	Corner of Sections 3	5 and 36
	Found 'T' iron w/cap #39089 Accepted as the best available evidence of the original corner position.				M-25 bears East, 2.0'
			3	CL Drain bears East & West Accepted as the best available evidence of the original corner position.	
⊃. De:	scription of monun	nent for corner and accessories esta	ablished to perpe	uate locating the position of t	the corner:
∵- 13	Meander Corne	er of Section 35	K-13	Corner of Sections 3	5 and 36
	'T' iron w/ca	ър #39089		Set ½" iron w/cap #3	9089 in mon box
	Tag in 16" As	st drain bears North, 15.0'sh bears East 39.0'sh bears S36°E, 37.0'		Tag in guard rail po Tag in guard rail po	st bears N17°E, 94.1′ st bears S67°E, 29.0′ st bears S21°W, 76.0′ st bears N13°W, 116.9′
	D 0)(1			JAMES I. W