Common to:

A13 - McKinley Twp. - T17N-R10E A01 - Winsor Twp. - T16N-R10E M01 – Fair Haven Twp. – T16N-R9E

1998 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE 190 Filing Requirement of Act 74, Mich. P.A. 1970

		9						
For (Corners in	Located in:	Corner Code #		1	STATE OF MIC	HTGAN	
1. F	(County) Public Land survey	Fairhaven T <u>17 N</u> R <u>9 E</u> TR TR	M-13 1	SUTVEY A SOME MALERY JAN 2 8 199		HURON COUR RECORDED 1 DEC 98 9:4	NTY D	
İI	Property Controlling n Section Miscellaneous	T R S T R S T R S T R		-SE OTION	ı	FRANCES L. HE	DEEDS	
		Recorded Plat	**************************************		syrster of Deeds	oramb & the r		
, <u>Ja</u> do her n lines currer Manag bove Court	mes T. Meek reby certify that under red s 1 and 2 above were in at manual of survey instru- gement or by a decree of were in conformance wit of Law; established, re- sed below:	, in a field survey on _October 3: quirements of P.A. 74, Michigan P.A. of conformance with regulations and rules t actions of the United States Department a Court of Law and/or that the corner po th the rules of the Michigan Board of Lan established, monumented, re-monume	0 , 1 1970, the corner points thereof as required in the of the Interior, Bureau o pints mentioned in lines of ad Surveyors or by a Dec nted, recovered, found	mentioned e f Land 3, 4 and 5 cree of a as	5 18 7 18 3 3	17 16	3 2 10 11 15 14 22 23 27 26	13
VOTI	e: Not more than 4 on this certifica	corners, all in the same town a te.	nd range, may be i	ecorded	12 31 3	32 33 3	34 35	36
		l monument and accessories and/ th Bdy. T17NR10E, 1835, H						
-13	Post	er of Section 36	:	Corner of To Ranges 9 and Post	-	and 17 Nor	rth,	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South 4 Corner of Section 36

Recorded surveys: none

No other tree near

LCRC: none

There is no remaining evidence of original corner position

County surveyors record: none

M-13 Corner of Townships 16 and 17 North, Ranges 9 and 10 East

> Found 4" iron in mon box 4' East of CL Bay Port Rd.

Lynn 14", \$47°E, 23 links Elm 12", N37°W, 504 links

Recorded surveys: none

LCRC: none

County surveyors record: axle shaft

Accepted as the best available evidence of original corner position

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

South 4 Corner of Section 36

At proportionate distance

Set 3" iron w/cap #39089

Signed by

From which: CL East & West drain bears North 4' CL Drive bears East, 18.0' Tag in PP bears \$15°W, 146.5' 4" conc post w/4" iron bears N2°W, 18.6'

Corner of Townships 16 and 17 North, Ranges 9 and 10 East

4" iron in mon box

From which: Tag in PP bears \$70°E, 76.9' Tag in 12" Elm bears S40°W, 58.9' 'y' iron bears N45°W, 28.0 ١٤" iron bears N45°E, 20.0°

Date December 8 1998

NSEO LAND . REVISED, M

MANAGERIAL PARTIES

OF MICHIG

Survevor's Michigan License No. <u>39089</u>

APPROVED AT PEER BOARD MEETING, 11-24-98