## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in Huran		qui on on her 14, when.
	(Социју)	Located In:	Corner Code ≠≠
1.	Public Land Survey	T IBN R LEE	C9
		T R .	
		T R	
		TR	· — — · · · · · · · · · · · · · · · · ·
2.	Property Controlling	S	
	in Section	S . T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. . Recorded Plat

5. Private Claims

4 Gary C. Bilow April 20, 1993 , in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: C9: Post established by U.S. Deputy Surveyor H. Parke in 1835 - accessories: B. Ash 14 N33-1/2W 16 and Cedar 14 S25-1/2W 13. C.M. Cade. a Registered Civil Engineer. in 1928 performed a survey of the Huron State Park (now known as Sleeper State Park) in which he records a "Cedar Post" but lists no accessories. Department of Conservation Surveyor D. Scott's (PS \$12029) retracement survey of Cade's survey in 1964 does not list what was recovered but lists accessories: N2W 39.0'. 6" Box Blder: S70E 60.7'. Twin 8" Poplar: S48W 49.0°. Corner Fence Post. Corner recorded under Act 74 PA 1970 by L. Feindt (PS #21566) in 1981 in Liber 1 Page 41 as "Found 1" solid rod centerline Conkey Road - raised with T-iron - accessories: North-39.40'-16" Ash. S70E-61.00'-10" Poplar. and S40W- 50.25'-20" Ash". S. Case (PS #15399) on a 1983 survey records "Found steel pin - accessories: Worth 39.15' to spike in E. side of 15" Blder. S20W 49.0" to spike in NE side of 36" Elder, and N45E 31.45' to top center E. end 15" Concrete Tile".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C9: Found T-iron in centerline Conkey Road at centerline Drive to South and one (1) of Feindt's witnesses and one (1) of Scott's witnesses. Accepted T-iron as the best evidence of the original GLO post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C9: Left T-iron in place

\$54W 49.13', Mail & Tag in North side of

corner Fence Post

\$38W 49.81'. Wail & Tag in Bast side of

24" Ash

S42E 36.60'. Nail & Tag in West side of

7" Poplar

WIE 32.78'. Center of a Telephone Box

BILOW ROFESSIONAL BUNVEYOR No. 28453

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971 REVISED MAY 14, 1975

PAGE 28