## Common to:

A01 - Huron Twp. - T18N-R14E M01 - Dwight Twp. - T18N-R13E M13 - Port Austin Twp. - T19N-R13E

> Re-Mon. Liker 2, Page 46 1999 REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in Port Austin Township

Huron (County)	Located in:	Corner Code #
1. Public Land Survey	T 19N R 14E T R T R	
2. Property Controlling in Section S. Miscellaneous Property in Sec.	T R	

STATE OF MICHIGAN HURON COUNTY RECORDED

30 DEC 99 2:17 P.H.

FRANCES L. HOLDWICK REGISTER OF DEEDS

Register of Deeds Stamp & File Number

FES U 2 2000

4	Lot No.	, Recorded Plat
٠.	LOUINO.	, recorded riot
_	<b>-</b>	OL :

Private Claims \_

SECTION

I, Russell L. Brown, in a field survey on Nov. 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. H. Parke D.S., Post Corners T18 and 19N, R13 and 14 East, Sugar 10 N28W 6, Do. 8 S4E 12 County Surveyors Records - None

County Road Commission Records - Dwight Twp., T18N-R13E, 1 N.E. Iron Pin App., Witnesses: P.K. P.P. S45W 56.05, Spike P.P. N45W 51.6' Spike P.P. N55E 65.9'

L.C.R.C. - None

Recorded Surveys: Liber 1, Page 41, Stewart G. Case, P.S. 15399, Found 1" Steel Pin Center of intersection:

Witnesses: Face P.P. N60E 65.6', Face P.P. N50W 51.0', Face P.P. S50W 55.5'

Unrecorded Surveys - None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original corner or accessories found.

Found 3/4" Iron in Monument Box

Accepted 3/4" Iron Found as best evidence of original Corner Position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A - 13, S.W. Corner Section 31, T19N-R14E

3/4" Iron in Monument Box

WITNESSES:

N45°W 51.84' to Spike in N.E. Side of Power Pole N50°E 65.90' to Spike in S.E. Side of Power Pole

S45°W 56.11' to Spike in S. E. Side of Power Pole

S45°E 49.69' to Notch in S. End C.M.P.

East 2645.23' to B - 13, S. 1/4 Corner Section 31, T19N-R14E West 2645.23' to L - 13, S. 1/4 Corner Section 36, T19N-R13E

Signed by Kussell S. Snown Surveyor's Michigan License No. 24588 Signed by

Date *Dec. 27, 1999* 

BROWN LAND SURVEYOR NO.

Peer group approved at meeting held 12 -27-99. RLB

This corner common with

M - 13, T19N-R13E

M - 1, T18N-R13E

A - 1, T18N-R14E