

123930

RECORDED

HILLSDALE CO. MICH.

'97 JUL 11 PM 2 48

Judy VanZandt
REC. OF DEEDS

LIBER 3 PAGE 178

HILLSDALE COUNTY REMONUMENTATION CORNER
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

ACCEPTED BY THE HILLSDALE COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1990 AT MEETING HELD ON
Al Ringenberg, C.P. Rep.
AL RINGENBERG, C.P. REP.

For corners in

HILLSDALE	Located In:	Corner Code
(County)		
ALLEN TWP.		
1. Public Land Survey	T <u>6</u> S R <u>4</u> W	G-4
	T ___ R ___	_____
	T ___ R ___	_____
	T ___ R ___	_____
2. Property Controlling in Section	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____
3. Miscellaneous Property in Sec.	S ___ T ___ R ___	_____
	S ___ T ___ R ___	_____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, EDWARD W. REED, in a field survey on JUNE 9, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
QUARTER CORNER COMMON TO SECTIONS 9-10

1876: GLO STONE & EARTERN & BRICK
1990: JOHN MAXSON, RLS- FOUND 1/2 IRON AN ACCEPTED AS CORNER: RECORDED IN LCRC # 611/379

SURVEY & REMONUMENTATION

FEB 11 1998

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON AS DESCRIBED IN LCRC # 611/379

SECTION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
SET 3/4"X30" REBAR IRON AND REMON CAP IN CI-MONUMENT BOX FLUSH WITH ROAD SURFACE


FACE OF POWER POLE N52E 46.58'
FACE OF POWER POLE N29W 59.55'
11" TWIN PINE S64W 45.6'
WOOD ANCHOR POST N31E 59.3'
C/L OF N-S ROAD EAST 1.0'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER

Signed by *Edward W. Reed*
EDWARD W. REED

Date APRIL 26, 1997

Surveyor's Michigan License No. 33985



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28
REVISED MAY 14, 1976

REVISED JAN., 199
REVISED OCT., 199