

44

For corners in

127741

LIBER 3 PAGE 200 HILLSDALE COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED HILLSDALE CO. MICH.

'97 OCT 30 AM 10 18

July Vangands

Hillsdale Located In: Corn (County)	ner Code #	$\mathcal{O}^{\mathbb{R}}$	EG. OF D	EEDS	U S
1. Public Land Survey	<u>C-1</u>	SI REMON	JRVEY IUMEN		ON
in Section S T R  3. Miscellaneous S T R  Property in Sec. S T R		Register of Dee		& File	Numbe
4. Lot No, Recorded Plat 5. Private Claims	1	A B G D E	ECTION F G H	I J	· К 1
Frederick J.    Cutcher	2 3 . 19 97 do hereby state that under 4	7 8	- 4 3 - 3 - 10 - 9 10 -	2	11
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mel conformance with regulations and rules therefore as required in the curre United States Department of the Interior, Bureau of Land Management of that the corner points mentioned in lines 3, 4 and 5 above were in confe Board of Land Surveyors or by a Decree of a Court of Law, estate	entioned in lines 1 and 2 above were in rent manual of survey instructions of the or by a decree of a Court of Law and /or formance with the rules of the Michigan	18 17	1615-	14	<b>1</b> 1

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

Original Government Survey by William Brookfield, 1825: W. Oak 13" S. 20° E. 15 links: W. Oak 11" S.  $53\frac{1}{2}$ ° W. 27 links.

Records of Ringenberg Engineering, 6/5/72: Set R.R. spike 48.84 feet (GLO = 48.84) East of S.E. Corner, Section 31, T6S, R3W, Hillsdale Township.

No references given.

7

recovered, found as expressed below:

on this certificate,

B. / Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On 9-22-97 I found a R.R. spike per above.

No witnesses were found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced R.R. spike with County remonumentation bar and cap in a monument box and is accepted as best available evidence of the position of the original corner.

In centerline Bankers Road.

Nail & spotter N.E. side util. pole N. 60° W. 45.30'

N.E. cor. church ramp S. 13° W. 31.70' N.W. cor. church S. 54° W. 74.00'

Nail & spotter S. side power pole N. 72° E. 71.25'

Surveyor's Michigan License No.

October 29, 1997 Date

REDERICK J CUTCHER POFESSIONAL No. FESSION

REVISED OCT. 1995

24592