1993

COMMISSION

"FORDED 一門。 以LE CO, MICH.

REMONUMENTATION

'93 DEC 27 PM 3 38

LIBER 3 PAGE 29

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REG. OF DEEDS

	HILLSDALE	Located In:	Corner Code :##
	. (County)	, 2000.00	<u> </u>
1.	Public Land Survey	7S 3W	$G-1$ $\left(\begin{array}{c} 1-1 \end{array}\right)$
1.	rubiic Land Sulvey	, TR	
		T R	
	,	T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

Register of Deeds Stamp & File Number

10

12

___ , Recorded Plat ___ Lot No. Private Claims _

John E. Maxson 27 December in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO, 1823, 30 Oak, S64W, 59 1ks

G-1

22 Sugar, S32E, 114 lks

LCRC, 1988, Ringenberg, L575, P214 Rebar

GLO, 1823, 24 Elm, S08E, 17 lks 14 Beech, S31W, 40 Iks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron from Ringenberg LCRC and accepted as the best available evidence of the position of the òriginal Corner

Found Iron at record offset and accepted as the best available evidence of the position of the original Corner

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-1 reset 5/8 x 36 rebar with cap reset 5/8 x 36 rebar with cap 18.00' NIOE 15"Maple South 12.97' 20"Maple NOSW 14.76' 15"Maple 17.80% 43.68' S25R 30"D.Maple West 52.671 P.Pole S25W 40.50 24"Maple 3.81' Fence Post East 53.46' G-13 @ T6S-R3W

OF MICHIE JOHN E. MAXSON SURVEYOR Nο

Date 27 December, 1993

Surveyor's Michigan License No. ____27454

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975