127745

RECORDED HILLSDALE CO. MICH.

'97 OCT 30 AM 10 19

For corners in

-; (°(;

LIBER 3 PAGE 204 HILLSDALE COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Hillsdale (County)	Located in:	Cor	ner Code#	
1. Public Land Survey	T <u>7s</u> F	R4W	K-3	
14 ₁₃ .	<u>T</u> R			
pin.	TR			
2. Property Controlling in Section	S TR			
Miscellaneous Property in Sec.	S TR			
	<u> </u>	`——		

SURVEY & REMONUMENTATION

TR	FEB 1 1 1998
in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	SECTION Register of Deeds Stamp & File Number
4. Lot No , Recorded Plat 5. Private Claims	ABCDEFGHIJKL
Frederick J.	2 6 5 4 3 2 1
Cutcher , in a field survey on 9/22 , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan	3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	7 8 —19 — 20 — 21 — 22 — 23 — 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 28 27 26 25
	11 32 33 34 35 36
A Description of original monument and accessories and/or subsequent restoration: Original Government Survey by William Brookfield, 1825: W. W. Ash 14" S. 31½° W. 25 links.	Ash 18" N. 30° E. 7½ links;
Ringenberg Engineering: A.J. Hatt set a R.R. spike in 1971; centerline of pymt. At 1320.15 found old 1/8 line fence extended from South at 5320.50 met.	nded from South, at 2640 30

of pymt. assuming the road to be best evidence of location of cor. No fnc. exists to North or South"; P.K. N.W. side 24" dbl. Maple N. 45° E. 38.80'; P.K. N.E. side 42" Maple S. 55° E. 54.52'. 31.1 B: Description of corner evidence found and/or method applied in restoring or reestablishing corner:

On 9-22-97 I found a R.R. spike in centerline of pumt. Above references are gone. From evidence of references found, this corner has been used by other surveyors.

found old 1/4 line fence extended from South, at 5280.50 set corner at centerline

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced R.R. spike with Hillsdale County remonumentation bar with cap in monument box and is accepted as best available evidence of the position of the original corner.

In centerline of Bankers Road. 61'± East of property line fence running North Found P.K. N.W. side power pole S. 56° W. 56.50' Found P.K. S. side R.R. tie cor. post N. 62° W. 66.90' Top center tel. stan. S. 75° W. 103.70' S.E. cor. conc. headwall to C.M.P. S. 85° E. 128.0'

igned by Areduck uveyor's Michigan License No. Frederick J. Cutcher 24592

October Date

10/9/97

REDERICK CUTCHER TROFESSIONAL SURVEYOR 24592 OF ESSION! ESSION ESSION