DEC 1 5 1993

LIBER 3 PAGE 3

COMMISSION

87702

BEDORDED UALE OO. MICH.

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'93 DEC 8 AM **8** 47

Hillsdale		•		On a Mariana	
		Located In:	Corner Code ##	REG. OF DEEDS	
1.	Public Land Survey	T <u>8S R 1W</u> T 8S R 1W	G-13 H-13	•	
	•	T R . T R ,			
2.	Property Controlling in Section	S T R S T R			
3.		S T R R		Register of Deeds Stamp & File Number	
	Property in Sec.	S			
4.	Lot No , F	Recorded Plat	*	A B C D E F G H I J K L !	
5.	Private Claims		<u> </u>		
				3	
	•	•		4 7 8 9 10 11 12	
١, _	R.Timothy Tietsema	, in a field survey on Novemb	er 12 , ₁₉ 93	_ , 5	
		quirements of P.A. 74, Michigan P.A. on conformance with regulations and		01.10 1 17 1 16 1 16 1 14 1 10	
		ructions of the United States Departr	•		
Ma	Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5				

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

G-13)

expressed below:

1823-GLO: Set original corner 65 links (42.90') East of Post

between Sec. 03 & 04, T9S, R1W.

on this certificate.

Ringenberg Records (date unknown) Fnd Stone w/"X" on top

14" Maple N40W 40.0' NW Bldg Cor S40E 66.3'

NE Cor Sec 4 T9S, R1W WEST 42.8'

12/9/1970 Kurzy: Fnd large Stone, Replaced w/Iron 7/17/1980 A. Ringenberg LS#15103: Fnd Boat Spike

NW Bldg Cor \$55E 65,94'

Description of corner evidence found and/or method applied in restoring or reestablishing corner: H-13)

G-13)

Found Boat Spike from the following:

1" Iron Pipe WEST 43.20' (NW Cor. Sec. 3, T9S, R1W) 24" Maple N07W 30.84'

NW Bldg Cor S40E 65.90'

Found 1" Iron Pipe from the following:

H-13)

Iron

Elec. Pole

12

S55W 68.00'

WEST 38.38'

7/17/1980 Allen Ringenberg LS#15103: Fnd Iron Pipe

1823-GLO: Set Original Corner.

Utility Pole S75W 68.95' 1/2" IR WEST 38.36'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13) Section Corner 33 & 34, T8S, R1W

Found Boat Spike per A. Ringenberg's Records (LS#15103), and is accepted as a careful and faithful reestablishment of the position of the original corner. Replaced with a 1" Iron Rod with Hillsdale County Remonumentation Cap.

PK Nail 24" Maple N60W 56.19' PK Nail 22" Maple N20W 75.66"

S40E **NW Bldg Cor** 65.90

NE Bldg Cor WEST 77.82'

1" IP (NW Cor. Sec. 3) T95, R1VV) ... WEST 43.20

H-13) Section Corner 34, T9S, R1W

Fnd 1" Iron Pipe per A. Ringenberg's Records (LS#15103) and is accepted as a careful and faithful reestablishment of the position of the original corner. Replaced with a 1" Iron Rod with Hillsdale County Remonumentation Cap.

Nail Utility Pole S75W 68.95' PK Nail Utility Pole S65E 192.82' PK Nail Dbl 10"Birch N65W 225.22" PK Nail 24" Maple N45W

1/2" Iron Rod WEST

Signed by _ Surveyor's Michigan Libense 19 20712

NO. 20712

FRED LAND SUR

10

Date December 7, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

38.36

REVISED JAN., 1983