

LIBER 3 PAGE 119 REMONUMENTATION

TEGRDED HELOUALE CO. MICH.

118386

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

'96 DEC 19 PM 2 19

For corners in		i iiiig iicqu	it content of Act 74, miles		_				
HILLSDALE			Corner Code ##	1	arily	, Va	~3~~	- <i>12</i> -	
(County)		Located In:			$Q_{\rm max}$	i Vo. Gerbee		100	
1. Public Land Su	ırvey	T _ 9S R _ 3W	C-3		1:12	. VE DEE	.D2		
		T R	Annual Control of the						
		T R	f						
		T R	The second secon						
Property Contri	olling S $_$	TR							
in Section	S	T R							
3. Miscellaneous	S	T R	error on waterproper sector of months, and months, action in the section and described his solution	Registe	er of Deeds	Stamp &	File N	ımber	
Property in Sec	c. S	T R							
4. Lot No	, Recorde	ed Plat	I Additional and make an an among many to a side of the species of		A B C f				
					ABC) E F G	H 1	JK	L M
				2	65		_ 3	- 2	-
			•	3			\perp		┦
	•			4	_ _ _		_10	_11	 -12—
JEFFREY BIESZ		ield survey on	10 DECEMBER 19	96 5			ĨL	ΪL	Ĭ.
	under requiremer	nts of P.A. 74, Michigan P.	A. of 1970, the corner points m	entioned 6			[
		•	and rules therefore as require artment of the Interior, Bureau	ed in the		l'i	_;;		
			ner points mentioned in lines (J UI Lanu					1
			d of Land Surveyors or by a De	cree of a	19 20	21-	-22	-23	-24
	blished, re-estab	lished, monumented, re	e-monumented, recovered, f			- - - 	++	+	+
expressed below:			•	10	3029	28	-2 7	-26	-25
NOTE: Not more	than 4 corners,	all in the same town	and range, may be record	led 11		-		+	+-
on this ce	rtificate.			12	3132	233-	_34	-35	-36
				13					
 Description of 	original monum	ent and accessories a	ind/or subsequent restorat	ion:	•				
1837 GLO		MARK		KELLER SURVEY I	IRED 547 PA	VCE 030			

POST 15 ELM S22W 8 lks 16 W. ASH S62.5E 30 lks STAKE UNDER BRIDGE 6 APPLE N66.75E 116.75 lks SET PK AT INTERSECTION OF CARPENTER RD AND TERRITORIAL ROAD AT 148 FEET WEST OF CORNER IN BRIDGE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

GEORGE MARK FOUND STAKE IN RIVER AND UNDER BRIDGE. I DID NOT FIND THIS STAKE BUT THERE HAS BEEN LOT OF ROAD WORK IN THIS AREA. FOUND PK SET BY KELLER AT INTERSECTION OF ROADS AND TIED INTO HIS SURVEY AND REESTABLISHED THE CORNER. THIS LANDED ON THE BRIDGE, AND SET A PK. ALSO SET TWO WITNESS CORNERS ON EITHER SIDE OF THE BRIDGE.. THE PK IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

> SUMVEY & REMONUMENTATION

> > MAY 1 6 1997

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3: SET PK ON BRIDGE NW COR BRIDGE RAIL N75W 26.09 NE COR BRIDGE RAIL N65E 22.63' SE COR BRIDGE RAIL SOUTH 15.81' SW COR BRIDGE RAIL \$55W 46.26

Surveyor's Michigan License No.

WITNESS CORNER WEST 40' WEST C-3 ON SECTION LINE NW COR BRIDGE RAIL N40E 18.21' SW COR BRIDGE RAIL S05W 16.00' R/W MARKER N35W 83.17 24" OAK \$40W 76.80' SET 5/8" x 36" REBAR IN MON BOX

WITNESS CORNER EAST 30' EAST C-3 ON SECTION LINE NE COR BRIDGE RAIL N20W 13.03' SE COR BRIDGE RAIL S35W 32,70' SOUTH RAIL EAST POST N50E 43.21' NORTH RAIL EAST POST N45E 46.00' SET 5/8" x 36" REBAR IN MON BOX

MINIMUM MINIMUM OF MICHIGAN A. BIESZK SURV.
No.
41093

Date 12 DECEMBER