8 PAGE 319

LAND CORNER RECORDATION CERTIFICATE

34 34

Filing Requirement of Act 74, Mich. P.A. 1970

Hov 22 11 48 AM '94

	r corners in APK L	MOIL	BUNKER HILL	FIGGSTER OF DEEDS
_	INGHAM	MISSIC Located In:	Corner Code ://	FROHAM COUNTY, MICH.
١.	Public Land Survey		E-9	
		T R		
		T R	and the control of the control of an area after the area of the control of the co	
		T R		
2.	Property Controlling	S		
	in Section	S T R		
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R	v. , , p. pare v gra programa per record d'unitable 2013	

, 19⁹⁴ June 21, Maurice H. Mahicu , in a field survey on . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

Description of original monument and accessories and/or subsequent restoration:

Original GLO survey done by Joseph Wampler between January 30 and February 8, 1826. "Set a post at a distance of 80.00 chains" distance of 80 chains, witnessed by:

11" Tamarack S 51° W 86

Private Claims ...

expressed below:

12" Tamarack S 40 1/2° E 213

- T. J. Brown utilized corner February 10, 1848 in survey by county surveyor. No Witnesses given. 2. Liber 3, Page 178, Ingham County Surveyors Records.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Found 1" x 24" iron bar in North-South-East and West fenceline, area is low and wet, comer falls 22 feet West of centerline of North running drain and 10 feet South of East running drain. Found 4 of Ron Lester's witnesses A-3. Accepted I" iron bar as position of corner, based on work performed by Ron Lester and no other evidence to displace location of corner. Removed I" bar and set 3/4" x 24" smooth bar with cap P.A. 345 P.S. #28414.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" x 24" Iron Rod was left in position and witnessed by: Nail and Tag #18998 East Side 28" Maple, N 30° W 25.62' Nail and Tag #18998 Northeast Side Twin 12" Maples, S 70° W 31.02'

Nail and Tag #18998 South Side 36" Maple, S 75° E 45.73'

Nail and Tag #18998 North Side 28" Maple, S 20° W 43.09'

Found 1/2" iron rod N 65° E 23.57 feet w/Lath #P5 07-30

Signed by _ #28414 Surveyor's Michigan License No.

REVISED MAY 14

MAHIFU

P.A. 345 INGHAM COUNTY PEER APPROVED 10/12/94 HL

(Continued)

Recorded and remonumented in July 24, 1990, Field Survey by Ronnic M. Lester, Land Surveyor (L-7, P-186). Investigation of corner revealed old North-South fence line West of North-South ditch line. Set 1" x 24" steel bar. Prorated old distances between E-8 and E-10 on old North-South fence line. Corner falls 12' West of centerline of North ditch and 10' South of centerlnie of ditch to East. Measured North 2640.2', South 2640.2', East 2644.3'. Witnessed by:

1" x 24" Steel bar 55 A-4165

Nail & Tag in Blaze, East side 24" Soft Maple, 332° Az, 25.6'

Nail & Tag in Blaze, Northeast side Twin 12" Soft Maple, 252° Az, 31.0'

Nail & Tag in Blaze, North side 20" Soft Maple, 200° Az, 43.1'

Nail & Tag in Blaze, Southwest side 24" Soft Maple, 113° Az, 45.8'

Corner referred to in July 1990 Act 132 survey (L-6, P-312) by Ronnie Lester P.S. #18998 with same witnesses as A-3.