DEC 1 7 1998

EECTON

		IER RECORDATION CERTIFI		9 Page	346
For corners in INGHAM TOWNSHIP	i mng rroqu			i ED	
INGHAM COUNTY	Located in:	Corner Code #	ti	LED	
1. Public Land Survey	T <u>2N</u> R 1E T R T R	A-12	09/29/1 REGISI Paul	0049407 1998 10:51:45 IER OF DEEDS La Johnson M COUNTY, MI	٠
2. Property Controlling S S	T R T R T R T R T R R T R R T R R T R R T R R T R R T R R T R		Register of De	eds Stemp &	File Number
4. Lot No, Recorded Pla	ıt				
5. Private Claims	···		A B C D B	F G H I	JKL
I, Maurice H. Mahieu, in a field survey on July 31, 1998, do hereby state that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Lend Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			3	- 9 10 15 15 15 15 15 15	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			9 10 30 29	2122-	2324
A. Description of original monument and accessories and/or subsequent restoration:			11	-28	2625
Corner not set in original government survey.			1 -3132	-3/33/4	3536
2. Corner referred to in a survey I 1847 (V.2, P.11).	oy A. Jackson, Cou	inty Surveyor, May 13,	131		•
3. Corner referred to in a survey i	oy G. Edwin States	, County Surveyor, November	25, 26, 1892 (V.3, P.:	204).	
			(Continued On Back)		
B. Description of corner evidence for	und and/or method ap	oplied in restoring or reestablishin	g comer:		
Found 1/2" rerod in 4" concrete momonument mangled; rerod bent, performed excavation in 1980. Exaluminum P.A. 345 cap #28414. T around.	All witnesses oblite cavated to point w	erated. No major excavation n here rerod sat plumb. Straigh	leeded as surveyor Le itened top of rerod and	ester d affixed	
C. Description of monument for co	rner and accessories	s established to perpetuate locatin	g the position of the cor	ner:	
Found 1/2" rerod in 4" concrete mo Witnessed by: Set Nail & Tag #28414 East side 18 Set Nail & Tag #28414 South side 5 Set Nail & Tag #28414 Northeast side 18 Set Nail & Tag #28414 West side 18	8" Hickory, S 20° W 16" Basswood, S 6: ide 14" Cherry, N50 0" Poplar, N 25°E,	V 73.07' 5° W 27.13' 0°W, 29.27' 64.97'	a #28414		
Signed by Maurier	- AMab	lien Date	9-17-98		-
Surveyor's Michigan License No. 2	B414				•
		FORM APPROVED BY M	CHIGAN STATE BOARD OF PROFE REVISED MAY (79, JAN. 20, 1971
			enderman medit.	R	EVISED JAN., 1983 EVISED OCT., 1995

P.A. 345 INGHAM COUNTY
PEER APPROVED BUIL 98 W

A. (CONTINUED)

4. LCRC recorded In Liber 6, Page 78 by Ronnie M. Lester PS #18998 on August 25, 1980. "Excavated a 6" x 24" hole to an average depth of 1.0" on the centerline of Kelly road and on fenceline east. Found no evidence of monumentation Corner considered lost. Set corner midway between A-13 & A-11 on standard Township line or Merklian. Measures North to A-11 2621.56"; measures South to A-13 2621.56"; measures North to M-11 Vevay 1386.16"; measured South to M-12 Vevay 1262.59". Corner falls in centerline Kelly Road and ±5.0" North of fenceline East. Witnesses to set 4" x 36" concrete monument with 1/2" x 38" rerod and cap #18998; Nail and Tag #18998 Southwest side 12" Cherry East-South-East 20.06"; Nail and Tag #18998 West side 24" Ash South-South-East 42.91"; Nail and Tag #18998 Southeast side 14" Hickory Southwest 41.58"; Nail and Tag #18998 Northeast side 12" Hickory, North-North-West 49.48"."

DE CONTRACTON

DEC 1 7 1998

SECTION

Rcpt Ho 97035 CRHR 9.00 MSSR 2.00 Total 11.00