REMONUMENTATION

JAN 1 8 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

in Section 3. Miscellaneous Property in Sec. S T R Property in Sec. S T R R Register of Deeds Stamp & File Number 4. Lot No. A B C D E F G II D A C D B C D B C D B C D B C D B C D B C D B C D D B C D B C D B C D D D D	For corners in ALAIEDON TOW	NSHIP	,	1	
T R Paula Johnson T R R Paula Johnson T R R R REGISTER OF DEEDS RECORDED Server The R REGISTER OF DEEDS RECORDED Server The R R REGISTER OF DEEDS RECORDED R	INGHAM COUNTY	Located In:	Corner Code#		
2. Property Controlling in Section S. T. R	1. Public Land Survey	T <u>3N R 1W</u> T R T R	Paula Johnson INGHAM COUNTY REGISTER OF DEEDS	BECUBICED	
5. Private Claims I, Maurice H. Mahieu, in a field survey on May 25, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:	3. Miscellaneous	STR STR STR	WOLVERINE ENGINEERS	2000-046391 Page: 1 of 2 10/31/2000 01	
A. Description of original monument and accessories and/or subsequent restoration:	5. Private Claims I, Maurice H. Mahieu, in a requirements of P.A. 74, Mic 1 and 2 above were in continuous in the current manual of surinterior, Bureau of Land Manathe corner points mentioned in rules of the Michigan Board established, re-established, mone NOTE: Not more than 2 corners	field survey on May higan P.A. of 1970, formance with regulati rvey instructions of th agement or by a dec in lines 3, 4 and 5 of of Land Surveyors of umented, recovered, for	25, 2000, do hereby state that unthe corner points mentioned in litions and rules therefore as require United States Department of ree of a Court of Law and /or tabove were in conformance with or by a Decree of a Court of Layring as expressed below:	der 2 6 5 4 3 the state of the	23-24-
	restoration:		·	12 31 32 33 34 3	536

- distance of 76.63 chains (5057.58') from I-3. "Int. N. Boundary 76 lks West of Post. Set post cor Secs 2 & 3 fw. Beech 10 S 39 E 15, Beech 20 S 57 W 35,"
- A L.C.R.C. recorded in Liber 1, Page 615 by Fred N. White L.S. #12034 on June 26, 1972 describes comer as a found 3/4" iron in a Monument Box in the centerline of Jolly Rd. with the following witnesses: 10" Cherry S 65° W 4.83'; 20" Maple S 05° W 34.52',
- An Act 132 survey recorded in Liber 1, Page 304 by Fred N. White L.S. #12034 on June 26, 1972 describes corner as a 3/4" pipe in Monument Box with the same witnesses as in A-2. No relevant measurements.
- An Act 132 survey recorded in Liber 1, Page 1079 by Ronnie M. Lester R.L.S. #18998 on January 3, 1974 describes corner as a Found Bar in a Monument Box. Corner measured 2359.97' from 1-2. Witnesses: MDSH Tag Northwest side Power Pole NE 90.54'; SE Corner Section 34, Meridian Twp., East 50.16'; MDSH Tag in East side 30" Maple South 34.56',

(Continued On Back)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1" outside diameter pipe in a Monument Box in the centerline of Jolly Rd. 50.14' West of I-13, Meridian Twp., and on a tree line South. Other witnesses obliterated. Accepted the 1" pipe as the perpetuated location for the corner, ignoring the inconsistency in monumentation descriptions of other surveyors. Affixed a 2 1/2" Aluminum P.A. 345 Cap #28414 to the 1" pipe.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: C.

'A 1" outside diameter pipe with a 2 ½" diameter Aluminum P.A. 345 Cap #28414 In a monument b	0X,
witnessed by:	
Set Noil and Tag #29414 (Most olds 7" Ulokan, S 24° M/ 22 82)	17.

Set Nail and Tag #28414 West side 7" Hickory S 24° W Set Nail and Tag #28414 SE side 9" Ash N 68° E 47.03'

Set Nail and Tag #28414 SW side 8" Ash N 36° W 28.74'

3/4" pipe with a P.A. 345 Cap #25832, in a Monument Box at I-13, Meridian Twp., East 50.14"

Surveyor's Michigan License No. 28414

Signed by

PROFL SURVL No. 28414 SOFESSION NO. 28414 SURVEYORS, JAN

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975

(A - Continued)

- An Act 132 survey recorded in Liber 4, Page 898 by Austin C. Williams R.L.S. #21275 on August 31, 1984 shows same 5. wilnesses as in A-2.
- An Act 132 survey recorded in Liber 4, Page 979 by Fred N. White, L.S. #12034 on February 13, 1985 references comer 6. to Liber 1, Page 615 (A-2).
- An Act 132 survey recorded in Liber 5, Page 288 by George M. Young, L.S. #17640 shows same monumentation and 7. witnesses as in A-2.

2000-046391 Page: 2 of 2 10/31/2000 01:29P

SURVEY & REMONUMENTATION

JAN 1 8 2001

SECTION