т.	Filing Requireme	LIBER ECORDATION CEI nt of Act 74, Mich Corner Code ##	8 PAGE 3 RTIFICATE . P.A. 1970	New 3'	FILE	15 Al 15 Al	105 1817		•	
<ol> <li>Property Controlling S T</li></ol>	RR		Regi	ster of	Deeds \$	Stamp	& File	Num	ber	
4. Lot No, Recorded Plat	vey on <u>SCDT</u> . 4. A. 74, Michigan P.A. of 19 with regulations and rub nited States Department ad/or that the corner point e Michigan Board of Lan	70, the corner points me es therefore as require t of the Interior, Bureau nts mentioned in tines 3 ad Surveyors or by a De	ed in the rof Land 8, 4 and 5 cree of a ound as	A B 2 6-3 3 4 7-5 6 18-7 8 19-9 9 10 30-30-	C D	E F	G H	14	K L	2- 3- 4- 5-
NOTE: Not more than 4 corners, all in to on this certificate.  A. Description of original monument and 1. Post set in original Government Ash 14" N84 W 31 W. Oak 18"	accessories and/or solutions:	subsequent restorati	ion:	11	the fol	lowin	g wit	nesse		6-
2. Surveyor Marvin Fouty LS #18 found 3/4" iron bar with the follow Nail & Tag in North side 26" Hick	989 recorded the c	il & Tag in West	side 38" Asl	h S45°	W 46.	-	Page 1	286 a	is a	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Searched at probable location of the corner and found the 3/4" pipe from witnesses in item 2 above. The corner is in a fill area of approximately 5' and occupies a position with extremely poor sight distance in both directions at the bottom of a valley. Dimensions for various surveys from the corner are: Fouty W 2629.98; Bryan W2629.83'; Fouty N2650.98'; Bryan N2651.03'; Bryan E2641.32'; White S2630.92'. Accepted the pipe as the perpetuated location of the corner because any other historical evidence at the corner location was probably obliterated in the construction of the road and the current location is in agreement with historical measurements and witnesses. Replaced the pipe with standard bar and cap and monument box.. Corner is 1' North of the centerline of Haslett Road on fence line to North in 5' of Road Fill. Field work conducted by David Clifford, PS No. 25837

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Standard 3/4" x 24" Ingham County Remonumentation Bar and PA345 Cap #18989 in monument box. Found Nail & Tag #25832 (Bryan) in 41" Ash, AZ 238°, 46.30' Found Nail & Tag #25837 in 24" Hickory AZ 246°, 70.25'

Found 1/2" bar and cap #18989 AZ 356° 33.08'

(Continued on Back)

Found Nail & Tag #25837 in SW side 13" Ash AZ 3340 29.87

Signed by Michigan License No. 18989

Date OCT: 30, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

P.A. 345 INGHAM COUNTY

REVISED HAT 14, 191

F. FOUTY

LAND SURVEYOR

LAND

- 3. Surveyor Marvin Fouty LS # 18989 reported using the corner in a survey dated Nov. 10, 1977 and recorded in Liber 3, Page 566 with the same monument and witnesses as item 2 above.
- 4. Corner recorded by Fred White LS #12034 in October 1979 in Liber 5 of Corners, Page 321 as a found iron beneath bit, surface with P.K. nail at road surface witnessed by:

Found nail & tag: NW side 40" Oak, S40°W, 46.35'

Found nail & tag: North side 24" Hickory, S45°W, 69.95'

Found nail & tag: SW side 6" Ash, N20°W, 30.19'

5. Surveyor Larry Bryan LS # 25832 reported using the corner in a survey in 1985 (85-B-5135) as a 3/4" bar with the following witnesses:

Set nail & tag E. side of 8" ash N20°W 30.19'

Set nail & tag NW side 40" ash S40°W 46.34"

Found nail and tag north side 24" hickory S60°W 69.91'

5. Surveyor Bryan again reported using the corner in a survey in 1992 (92-B-36413) as a found 3/4" pipe with the following witnesses:

Found nail & tag #25832 in east side 8" ash, N20°W 30.20'

Found nail & tag #25832 in west side 40" ash S40°W 46.34'

Found nail & tag #18989 in north side 24" hickory S60°W 69.91'

. Surveyor Bryan again reported using the corner in a survey in 1993 (93-B-41350) as the same monument and vitnesses as in item 6. B above.