SEP 01 1999

## 950003950 Liber8

Page571

SECTION

I AND CORNER RECORDATION CERTIFICATE

OLO HOI	Filing Requirement of Act 74, Mich. P.A. 197	0
For corners in	CITY OF EAST LANSING - MERIDIAN TWP.	FU.ED
INGHAM COUNTY	Located In: Corner Code #	11/28/1995 14:13:52 REGISTER OF DEEDS PAULA JOHNSON INGHAM COUNTY, MI
1. Public Land Survey	T_4N_R_1W	•••••
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	TR         ST_R         ST_R         ST_R         ST_R	Register of Deeds Stamp & File Number
4. Lot No, Record 5. Private Claims	led Plat	A B C D E F G H I J K L M  2 6 5 4 3 2 1 3 2 1 3 2 1 3
74. Michigan P.A. of 1970, the or regulations and rules therefore as Department of the Interior, Burez corner points mentioned in lines 3.	survey on Oct. 25, 1995 do hereby certify that under requirements of P.A. corner points mentioned in lines 1 and 2 above were in conformance with a required in the current manual of survey instructions of the United States au of Land Management or by a decree of a Court of Law and for that the 4 and 5 above were in conformance with the rules of the Michigan Board of the Court of Law; established, re-established, monumented, re-monumented, low:	4 - 7 - 8 - 9 - 10 - 11 - 12 - 15 - 14 - 13 - 7 - 15 - 15 - 14 - 13 - 7 - 15 - 20 - 21 - 22 - 23 - 24 - 1
NOTE: Not more that 4 con on this certificate.	ners, all in the same town and range, may be recorded	9
A. Description of original mo	nument and accessories and/or subsequent restoration:	12 - 1 - 32 - 33 - 34 - 35 - 39 - 3
as the original corner, "Int.	eputy Surveyor, set this corner on Thursday, Feb. 8, 1827 The West Boundary 15 lks S of the post Cor. Of Sect. 12 & post cor. To Secs. 7 & 18. Tam 14 N45E 53; Do 16 S15E	
2. On the MDOT plans for N40 E 44.55 22" Elm; ½"	M-78 dated 1953-56 the following was given for the corner: I iron rod in Monument box.	N50°W 52.53' 15" Elm; S65°E 40.96' P.Pole;
Found ½" iron rod in steel stamped #31603(Doug Rid Discussion with Mr. Stan I 1940's and any attempt to accepts the location of the	See Part A continued on be found end/or method applied in restoring or reestablishing corner: collar in centerline of Abbott Road and 5.6' South of centerline chardson) at location of M-5, Lansing Township, 9.92' N01°W Dewitt, City of East Lansing Engineering Department, revealed excavate below found ½" rod to find any evidence of original 9½" rod as the best location for the perpetuation of the corners in Part A-6. Replaced ½" rod with 3/4" x 8" iron rod mortare	e of Burcham Drive to East. Found cap  I. The iron in a concrete sub roadbed.  I that Abbott Road has been rebuilt in the corner would be fruitless. This surveyor  I. The witnesses in Part C will be in close

cap stamped "PA 345 PS 28414"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 3/4" smooth iron rod in concrete roadbed witnessed by:

Found bar and cap #31603 N73"W 34.44 feet

Found MDOT nail and tag north side of Power Pole S57"W 32.13 feet

Found nail and tag #16053 east side of Power Pole S57°W 31.70 feet

Found PK nail north side of Power Pole S57"W 32.24"

Top of fire hydrant N48°W 44.22 feet

Found MDOT nail and tag north side Power Pole S70" E 48.06 feet

Found nail and tag #16053 west side Power Pole S70"E 47.72 feet

Found PK nail north side Power Pole S70 E 48.37 feet

Northwest corner of Brick Building S55°E 57.32 feet

Southwest corner of Brick Building N44, E 75.61 feet

Signed by

Surveyor's Michigan License No. 28414

REVISED MAY 14,1975 REVISED JAN, 1983

P.A. 345 INGHAM COUNTY OVED\_ PEER

## Part A Continued

- 3. Ingham County Road Commission old grid map notes the corner as a ½" iron rod in a monument box, witnesses by: 24" Elm N32°E 43.94 feet 20" Elm N65°W 52.22 feet 9" Spruce S87°W 50.04 feet Light pole (face of base) S38°E 36.02 feet
- 4. Ingham County Road Commission 1972 revised grid map notes the same as A-3 above.
- 5. An Act 74 LCRC was recorded by Nelson Jones PS 02934, MDOT, in Liber 1, Page 295 on Dec. 7, 1971 as A found ½" iron in monument box. LCRC Part B "It will be noted that NW corner indicated on the plat of "College Grove" is the Section Corner common to Sections 12 and 13, T4N, R2W.; it appears that the surveyor making the plat used the standard corner, instead of the closing corner" Witnessed by: 0.6' west of Centerline of pavement of Abbott Road; 5.6' South of Centerline of pavement of Burcham Road; N45°E 75.64 SW corner Building #700; S55°E 67.28' NW corner Building # 656; N40°W 44.34' Top of fire hydrant.
- 6. An Act 74 LCRC was recorded by James E. Stephens PS 16053 was recorded in Liber 2, Page 593 on Nov. 29, 1973. A ½" iron rod in A monument box was found in the centerline of two section line roads. Witnessed by:

Survey tag in the West side of A utility pole, S64°39'E 47.49 feet Survey tag in the East side of A utility pole, S57°44'W 31.82 feet N40°09'W 44.30 feet to the center of A valve stem on A fire hydrant

- 7. An Act 132 Certificate of Survey was recorded by James E. Stephens PS 16053 in Liber 1, Page 841 on Jul 30, 1973. The monumentation and witnesses are the same as A-6 above.
- 8. An Act 132 Certificate of Survey was recorded by James E. Stephens PS 16053 in Liber 2, Page 973 on Feb. 7, 1977. The monumentation and witnesses are the same as A-6 above.
- 9. An Act 132 Certificate of Survey was recorded by James E. Stephens PS 16053 in Liber 3, Page 1100 on Dec. 28, 1979. The monumentation and witnesses are the same as A-6 above.
- 10. An Act 132 Certificate of Survey was recorded by James E. Stephens PS 16053 in Liber 3, Page 1101 on Dec. 28, 1979. The monumentation and witnesses are the same as A-6 above.
- 11. An Act 132 Certificate of Survey was recorded by James E. Stephens PS 16053 in Liber 7, Page 77 on Jan 19, 1994. The monumentation and witnesses are the same as A-6 above.

SURVEY & REMONUMENTATION

SEP 01 1999

SECTION