## REMONUMENTATION

## COMMISSION

Surveyor's Michigan License No. 25863

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	3	· · · · · · · · · · · · · · · · · · ·		, <b>.</b>
Ionia	Located In:	Corner Code ##	æ €	93 <sub>M</sub>
(County)			(G) (G) EGIS	
1 Dublic Land Company	T <u>5N</u> R <u>5W</u>	A-5	STE	
Public Land Survey	T R	A=J	23	27 27
	T R		, m	<b>~</b> '925
	T R		₩ <b>&amp;</b>	P1
2. Property Controlling	S T R		SS &	1 :05: 1 เด็มมี หชั่
in Section	S T R		5	.05 विस्तृति सर्
3. Miscellaneous	S T R		Register of Deeds Stamp	& Eile Number
Property in Sec.	S TR		register of Deeds Stamp	o a rife Humber
• •	•			
4. Lot No, R	lecorded Plat		- ABCDEF	GHIJKLI
5. Private Claims				
			2 6 5 4	
•			3	
	* <del>**</del>		4 - 7 - 8 - 9 -	10-11-12-
	, in a field survey on <u>Octob</u>		, 5	
		of 1970, the corner points mentioned		15 14 13 13
		d rules therefore as required in the ment of the Interior, Bureau of Land		
· .		r points mentioned in lines 3, 4 and 5	1 1 1 1 1 1	
		f Land Surveyors or by a Decree of a		1 1 1
Court of Law; established, re expressed below:	e-established, monumented, re-m	nonumented, recovered, found as	10 30 30 38	
·		#	11   29   28	27 26 25
	orners, all in the same town an	d range, may be recorded		
on this certificate.			12 31 32 33	34 35 36
A. Description of original n	monument and accessories and	/or subsequent restoration:		
survey April 18, 18 Surveyors Records. Surveyor's copy of Sugar S 13° W 134 1. The Ionia County Rod Highway was being re set a 3/4" iron nex B. Description of corner ev Found Arkrom's 1/2" a 3/4" iron. Dug de East of Ankrom's roc	90 in Section 18, T5N-Crawford's witnesses the G.L.O. notes: He /2 links. He did not ad Commission shows wi econstructed in 1962. t to it. This corner ridence found and/or method a rod and cap just belown to 24" and found of	C. Crawford former Ional R5W which is found in to this corner are for states: 1891, 3" Swamp state what was set for itnesses to this corner. The road commission is was recorded by Profest population restoring or reestablishow the pavement. Dug is alay cylinder next to it the position of Ankrold	Volume 2 page 120 und as marginal not p Cak N 40° E 77 lir the corner. r which were taken found a 2 1/4" clay ssional Surveyor, Duhing corner. beneath and at a deiron. The 3/4" iro	of the County es in the Cour nks and 10" when Keefer cylinder and ane Ankrom(ove pth of 20" foun m was about 0.
•				
Set a 20" fiberglass		stablished to perpetuate locating Liameter bronze cap sta		
	t side power pole N 29	° w 58.11"		
Nail & tag Southeast Nail & tag top cente Nail & tag Northwest	side power pole N 25 er right of way monume side power pole S 49 Section 13, T5N-R6W N	° E 43.41' nt S 32° E 40.95' ° W 61.46'		
•		- 1		
Signed by	ud a omike	oliz Novom	nber 2, 1993	
/191100 Dy	<del>_</del>			

Con't B: #21265 in April of 1977 found in Liber 1 page 228 of Ionia County records. Ankrom states he found a 3/4" iron 1.5 feet below surface 0.3' East of the Township line. He set a 1/2" rerod and cap opposite the 3/4" iron & on the Township line. Professional Surveyor, Russell Roon number 13593 rerecorded Ankrom's corner in November of 1978, found in Liber 2 page 87.

