FEB 1 5 2001

SECTION

## IOSCO COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Surveyor's Michigan License No. #41108

For corners in	гинд н	kequirement	of Act 74, Mich. P.A	. 197	70		01	0	2	00	). ¥				
IOSCO (County)	Located In:	Corner Cod	e #					•	2000		F t				
Public Land Survey	T21N R 5E						STATE OF MICHIGAN 10SCO COUNTY FILED								
Property Controlling     In Section	T R S T R S T R		· · · · · · · · · · · · · · · · · · ·							24 AM					
Miscellaneous     Property in Sec.	S T R S T R		<del></del>			R	BONIT EGIST	er o	F DEE	DS					
				L		Regis	ster o	f Dee	ds S	tamp a	& File	Numl			
4. Lot No, Recorde 5. Private Claims	d Plat	· · · · · · · · · · · · · · · · · · ·				D	0 0	-							
					1			- E	G	<u> </u>		K			
					2	- 6 -	<del>  5</del>	+	4	— <u> </u>	- ż				
William J. Rigg, P.S., in	a field survey on Oct	ober 12 200	O do hereby state that un	ıder	3	-		-	1	_		+			
conformance with regulations and rule	'.A. 01 1970, the comer po es therefore as required in	ints mentioned i	n lines 1 and 2 above were	e in	4	7 	8 <del> </del>	_	9 —	10 	11	1			
outed others peparition of the inter	iidi. Biifeali of Land Manac	compant or by a de	oron of a Carril attack		5 - 6 -	10		1							
that the corner points mentioned in li Board of Land Surveyors or by a I	Jecree of a Court of Law	in contormance; ; established, r	with the rules of the Michig e-established monuments	gan ed	7				16—	—15— 	<del>14</del>	1			
read to real, lound as expressed below	•			,	8	-   9	-20		21	—22—	23				
NOTE: Not more than 2 coners, all in the same town and range, may be recorded on this certificate				9-		1-1		-		<u> </u>					
on this certificate					10	3 <u>0</u>	29	_	28	27	26	2			
					11		+	+-	$\vdash$		-				
					12	-31 <del>-</del>	32	<del>-   -</del> .	33-	34	35	30			
A. Description of original monum 1844 +/-, GLO Survey, set po	ost, 8" Tamarack, N40	nd/or subsequ E 14 lks, 7" C	ent restoration: edar, N33W 41 lks		13 <sup>L</sup>		1 <u></u>	1	4		<b>)</b> i	_1			
1950+/-, MDOT Highway M	aps														
1976 James Campbell, Set 1"	Bolt in Mon Box, Li	ber 248, Page	262												
1988 Northeast Land Surveys	s, Found 3/4" Bar in M	lon Box, Libe	378, Page 496						•						
B. Description of corner evidence	e found and/or method	applied in res	oring or reestablishing	corne	er:										
Found 3/4" bar in Mon Box	as evidenced by maps	and surveys,	witnesses check.												
				AC St	CE	EA M	FFR:	330 330	IOSC UP A	IO CO IS THE	UNT	Y			
				Or	FIC		/POC	ER	JNDE	ER P.A					
				HE	=1 N	ON	10-	1/-	700	20		_			
						Jan	ns.	H .	L	an	te	~_			
						,		, ,	·	$\overline{}$	7				
C. Description of monument for c	corner and accessories	established to	perpetuate locating the	posit	ion	of the	corne	er:							
Left 3/4" bar in Mon Box a West 3.0" centerline Highwa	and topped with Remon av M-55	n Cap.	E OF MICH	iu.											
N20E - 87.95' 10" Elm	-		MILLAND	Z THE											
N80E - 46.32' 8" Elm S40E - 49.27' 6" Elm			WILLIAM J. RIGG	· 本言	1										
S55W - 116.50' Power Pole			PROFESSIONAL SURVEYOR	POR WILLIAM											
	1		41108	THIRD.											
1/11	// m		OFESSIONAL MINIMUM	in.											

Date December 22, 2000

FORM APPROVED BY MICHIGAN STATE BOARD OF PROPESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975; REVISED JAN., 1983; REVISED OCT., 1995