FEB 1 5 2001

**SECTION** 

013 2001

## IOSCO COUNTY REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code #

For corners in

IOSCO

Located in:

(County)	CT spe se continue
1. Public Land Survey T22N R SE M-11 T22N R SE M-11 A-11	STATE OF MICHIGAN IOSCO COUNTY FILED
7 Property Controlling	13 FEB 2001 9:21:24 AM
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R	BONITA M. COYLE REGISTER OF DEEDS
Property in Sec. STR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	1 A B C D E F G H I J K L M
	2 6 5 4 3 2 1 1 3
1. William J. Rigg, P.S., in a field survey on October 12 2000 do hereby state that unc requirements of P.A. 74, Michigan P.A. of 1970, the comer points mentioned in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of t United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Supplements of the Property	der 4 7 8 9 10 11 12 12 14 15 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumente recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 coners, all in the same town and range, may be recorded on this certificate	9 10 30 29 28 27 26 25
	11 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration: 1844 +/-, GLO Survey, set post, 11" Birch, S42W 12 lks, 14" W. Pine, N17W 12 lks	13
1990 Phillip D. Case, Set 3/4" X 6' pipe in GLO position, See LCRC 90 - 13	
B. Description of corner evidence found and/or method applied in restoring or reestablishing of Found 3/4" Rerod as evidenced, witnesses check.	comer:
AC .	CCEPTED BY THE IOSCO COUNTY
Of 54	URVEY PEER GROUP AS THE FFICIAL CORNER UNDER P.A. 5 OF 1990 AT A MEETING FLD ON /0-1/-7000
	James H Shanger
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
Placed Remon Cap on existing 6' pipe.  S55W - 10" Ash - 8.22' S40E - 10" Maple - 35.24' N45E- 18" Maple - 29.14' S17W - Pine stump remains - 7.95' N62W - 8" Ash - 20.26'  Bigned by  Date  Dec	
1/// I	
	cember 22, 2000
Surveyor's Michigan License No. #41108	Form approved by Michigan Board of Professional Surveyors, Jan 28, 1971 Revised May 14, 1975, Revised Jan., 1985, Revised Oct., 1985