

SURVEY & REMONUMENTATION

DEC 13 1993

COMMISSION

IOSCO COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in _____

<u>Iosco</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>22N</u> R <u>6E</u>	<u>C-5</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

93-32
 FILED
 DEC 1 11 06 AM '93
 REGISTER OF DEEDS
 IOSCO COUNTY, MICH.
Denise M. Doyle
 Register of Deeds Stamp & File Number

I, James H. Granger, in a field survey on November 15-17, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1843 Original Survey, John Mullett
 - Set Wood Post
 - 14" Yellow Pine S31°W 5 lks.
 - 9" Hemlock N9°W 8 lks.
- 1931 Dependent Resurvey, Guy Veal

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- Fd. 3 1/4" dia brass cap on conc. cylinder
- No evidence of witnesses

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Left 3 1/4" dia brass cap on conc cylinder
- Set nail & tag PS#16041 in:
 - 14" Twin Birch S60°E 67.42'
 - 15" Maple S20°W 12.25'
 - Fence Cor. Post N38°E 21.15'
 - 10" Maple N42°W 45.37'



Signed by James H. Granger Date Nov. 30, 1993
 Surveyor's Michigan License No. 16041