## IOSCO COUNTY REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

96-75

For corners in	Filing Require	ement of Act 74, Mich. P.A.	1970
IOSCO			STATE OF MICHIGAN
(County)	Located in:	Corner Code ##	IOSCO COUNTY
	22M 05		FILED
Public Land Survey	T23N R 9E	<u>C-1</u>	7 350 07 040 B U
<b>*</b>	. T R		6 DEC 96 2:12 P.M.
	T R T R		DONITA H. COYLE
2. Property Controlling	S T R		REGISTER OF DEEDS
in Section	S T R		ingawian vi saled
3. Miscellaneous	S T R		Projetov of Daniel Co.
Property in Sec.	S T R		Register of Deeds Stamp & File Number
A Lathia I	B 4 1 B4 1	•	
5 Private Claims	Recorded Plat		A B C D E F G H I J K L
o. Trivate Olamb			2
			3
WILLIAM E WO	0.00		4 7 8 9 10 11
, WIBLAN E. WO	ODS in a field survey onN	OVEMBER 19 19 96	5
in lines 1 and 2 above were in	quirements of P.A. 74, Michigan P.A. on conformance with regulations and	if 1970, the corner points mentione	d 6 18 17 16 15 14 13
current manual of survey instr	uctions of the United States Departr	nent of the Interior, Bureau of Lan	d 71 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Management or by a decree of	a Court of Law and/or that the corner	Doints mentioned in lines 3, 4 and	5 1 1 1 1 1 1 1 1 1 1
Court of Law; established,	th the rules of the Michigan Board of re-established, monumented, re-m	Land Surveyors or by a Decree of onumented, recovered found a	a 9
expressed below:			10 30 29 28 27 26 25
	orners, all in the same town and	range, may be recorded	11
on this certificate.			12 31 32 33 34 35 36
A Description of original	manument and accessive and	(mm	13
	monument and accessories and GOVERNMENT SURVEY		
TOTOL ORIGINAL	GOVERNMENT SURVEY	SET POST C	ORNER 52 LINKS EAST OF POST
		10" PINE S48°E, 43	S81°W, 40 LINKS, 12" PINE
1947: R.J. COOK	Œ	TATE'S DIN	ECREST SHOWS COMMON CORNERS
•		WEST PLAT	BOUNDARY, IN ERROR. CORNERS
		SHOWN ON P	LAT IS SOUTHWEST CORNER OF
1987: GOURDIE /	EDACED & ACCOUNT	SECTION 32	, C-13, T24N, R9E,
1907: GOORDIE /	FRASER & ASSOCIATE	S BOUNDARY S	URVEY ON W.A.F.B. PROVES
		THIS CORNE	R TO BE 34.61 EAST OF
B. Description of corner ex	vidence found and/or method ap	plied in restoring or reestablis	wh on PLAT.
1006			
1996: WILLIAM E	. WOODS	FOUND 1" P	IPE 34.61 EAST OF SOUTHWEST
		CORNER OF S	SECTION 31, T23N, R9E.
		REPLACED 1'	PIPE WITH 5/8 ROD AND
		ALUMINUM CA	AP.
. ACCEPTED BY TH	IE IOSCO COUNTY		
SURVEY PEER GE OFFICIAL CORNEI	ROUP AS THE		
345 OF 1990 AT A	MEETING		
HELD ON 10 -	73-96	•	
James H	Granger	•	
V			
C. Description of monumer	nt for corner and accessories est	ablished to perpetuate location	ng the position of the corner
5/8 ROD WITH ALUN			ig the position of the dollier.
	1.43		
	0.08	OF MIC	THE STATE OF THE S
P.P. N52°E 42	2.99	Alle	1/1/2 B
TRIPLE 8" RED PIN	IES S15°E 44.66	WILLIAM E	- 2
		WOODS	· · · · · · · · · · · · · · · · · · ·
		LAND SURVEY	(OR: 5
		160. 21. 682	/ <u>~</u>
		TO LAND	SULTER
. 1 *	1	LAND LAND	TTATA
a Allah	ian & Wood	V	
Signed by/// \delta/b/		Date <u>NO</u>	VEMBER 19, 1996
Surveyor's Michigan License	No25882	FORM	APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
•			REVISED MAY 14, 1975

SURVEY & REMONUMENTATION

SEP 2 2 1999

SECTION